



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21013322/Avf3e2	
			Date: 25/07/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9475J	Veh. Inspected	GBF 4779E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103880/SYH	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	30/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NHR85	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JAANHR85EG7100316	Colour	BLUE	
Odometer	15122 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	KAPSEN	6 mm	
L/H Front Tyre	195 R15C	KAPSEN	6 mm	
R/H Rear Tyre	165 R13C	WINDFORCE	6 mm	
L/H Rear Tyre	165 R13C	WINDFORCE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2021	Inspection Date	31/12/2021	
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	