

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / ☒ P RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s KOMPRESSOR AUTO

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: JRH 4250

Yr Regn: 30 JAN 2016

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN ALMERA c.c 1498

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 262905 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PN8BBAN17TCB03524 *

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size: F: 205/50R16

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 19-01-2022

Survey held at W/S 11AM

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : W/Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Copy / MPB: