PRS Rec. By: GQ | REF: CS3/LPC21013330/Gtf3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s PAUL HOE

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $45k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKZ5141B Yr Regn: 26 Jan/ 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: NISSAN SYLPHY 1.6 c.c 1598

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading — T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MNTBBAB17Z0026622 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CONTINENTAL

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	31-12-2021

Survey held at W/S 12:30

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$2000 - $3000
	SUBMIT PRS REPORT

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LPC:

: Preli. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL