

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRES SINGAPORE 239924			Ref: CS/AGI21013337/Kvf3n2 Date: 28/01/2022 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 9488Y	Veh. Inspected	SLV 870Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10013109/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	30/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102082372	Colour	METALLIC BROWN	
Odometer	349007 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	NEXEN	4 mm	
L/H Front Tyre	215/60 R17	NEXEN	4 mm	
R/H Rear Tyre	215/60 R17	YOKOHAMA	9 mm	
L/H Rear Tyre	215/60 R17	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/12/2021	Inspection Date	13/01/2022	
Survey held at	LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		