

(08/11/13)

wef

ASS. REC. BY: Pam

REF:

CS/AK22000004/R1f3

378A

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

77K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMM 88433

Yr Regn:

2019 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA CERATO 1.6(A) EX

c.c

1591

Colour

WHITE

A/C:

Insured / Std / NI / NA

Sp. Reading

19863

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF3416MK5047586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/12/21

D.O.I.

03/01/22

Survey held at

CYUTCPH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 43K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

); S + RS, SI

☐

: Interview (\$

); Photos

☐

: Tech. Invs (\$

); Others

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



& CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TOH YING HUI ELAINE
	Reg No/Reg Date	SMM8843J / 18/07/201
	Date In/Mileage	31/12/2021/ 0
	Chassis No	KNAF3416MK5047586
	Engine No	G4FGKH741973
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	31/12/2021/ 13:18	BLK	282 / Kevin Leong	44940			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, SUPPORT, BONNET, FRT LH FENDER & AFFECTED AREA @ 400 X 4 REPAIR ON FRT RH FENDER					1600	2400.00		2400.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, FRT LH DOOR & BOTH FRT FENDER @ 350 X 5						1750.00		1750.00
E PNT88000 REMOVE & REPLACE RADIATOR, CONDENSER						120.00		120.00
M SUNDRY TO TOP UP AIRCON GAS						80.00		80.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA					60	80.00		4800.00
M SUNDRY PERFORM RUST PREVENTION					80	120.00		9600.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00		30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						120.00		120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME						50.00		50.00
M SUNDRY SUNDRIES					80	50.00		4000.00
M	LAMP ASSY-HEAD, LH				1.00	1219.00	20.00	975.20
M	LAMP ASSY-HEAD, RH				1.00	1219.00	20.00	975.20
M	HORN ASSY-LOW PITCH				1.00	74.00	20.00	59.20
M	RADIATOR ASSY				1.00	646.00	20.00	516.80
M	BLOWER ASSY				1.00	656.00	20.00	524.80
M	GUARD-AIR, LH				1.00	28.00	20.00	22.40
M	GUARD-AIR, RH				1.00	28.00	20.00	22.40
M	CONDENSER ASSY-COOLER				1.00	687.00	20.00	549.60
M	PANEL ASSY-UNDER COVER				1.00	117.00	20.00	93.60
M	DUCT ASSY-AIR				1.00	55.00	20.00	44.00
M	PANEL ASSY-HOOD				1.00	1502.00	20.00	1201.60
M	HINGE ASSY-HOOD, RH				1.00	43.00	20.00	34.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





& CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

### ESTIMATE

g No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TOH YING HUI ELAINE
	Reg No/Reg Date	SMM8843J / 18/07/201
	Date In/Mileage	31/12/2021/ 0
	Chassis No	KNAF3416MK5047586
	Engine No	G4FGKH741973
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	31/12/2021/ 13:18	BLK	282 / Kevin Leong	44940			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE ASSY-HOOD,LH	54			1.00	43.00	20.00	34.40
M	PANEL-FENDER,LH	54			1.00	430.00	20.00	344.00
M	PANEL-FENDER,RH	repair			1.00	430.00	20.00	344.00
M	CARRIER ASSY-FRONT END MODULE	cra			1.00	675.00	20.00	540.00
M	BEAM COMPLETE-FR BUMPER	?			1.00	497.00	20.00	397.60
M	PAD-HOOD INSULATING	de			1.00	156.00	20.00	124.80
M	GUARD ASSY-FRONT WHEEL,LH	?			1.00	95.00	20.00	76.00
M	COVER-FR BUMPER	turn			1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	?			1.00	262.00	20.00	209.60
M	GRILLE ASSY-RADIATOR	cra			1.00	328.00	20.00	262.40
M	GARNISH-RADIATOR GRILLE	?			1.00	38.00	20.00	30.40
M	MOULDING-FRONT BUMPER,LH	?			1.00	36.00	20.00	28.80
M	AIR DUCT-FR BUMPER,LH	?			1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY	cr			1.00	84.00	20.00	67.20
M	STIFFNER-FR BPR LWR	X			1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG	?			1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG	?			1.00	22.00	20.00	17.60
M	ORNAMENT-KIA NO.115	cr			1.00	32.00	20.00	25.60

SURVEYOR NAME: Rose - Hp 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 03/01/22 @ 1540

REMARKS: 8 days

EXCESS: TBA / REVIEW

Res before paint

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on **Nett** 12,948.00  
12948.00 **906.36**

**Total Payable** 13,854.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	31/12/2021 12:58 (SGT)
Date of Accident	30/12/2021 18:00 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	AYE AFTER ALEXANDRA ROAD EXIT 6
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM8843J
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TOH YING HUI ELAINE
NRIC No	SXXXX378A
Email Address	elainetoh.love@gmail.com
Mobile Phone No	(Phone) +65-97889345
Alternative Phone No	+65-97889345

### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900109936-01
Cover Note Number	-

### DRIVER



Driving Pass	18/03/1986
Experience	Indoor
	11/02/2012
	9 YEARS AND 10 MONTHS
Number	Female
Phone Number	(Phone) +65-97889345
Address	+65-97889345
Address complement	elainetoh.love@gmail.com
Postcode	BLK. 271 CHOA CHU KANG AVENUE 2
Is the driver the policyholder?	#10-259 SINGAPORE
If No, Relationship of the Driver with the Insured	680271
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	No
	-
	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML5656H
Vehicle Manufacturer	Nissan
Vehicle Model	Qashqai
Vehicle Variant	-
Vehicle Colour	Red
Vehicle Category	Private car
Name of Driver	WONG CHI KHUEN
Contact Number	(Phone) +65-81801696
Address	



Company Name	-
Damage	-
of property damaged in accident	-
Passenger (Including Driver)	-

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGM1200G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	JERRY TUN KIN SENG
Contact Number	(Phone) +65-91716717
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan






### Describe Circumstances of the Accident

On 30/12/2021 (Thursday), at about 6pm, I was travelling on the AYE on the first lane headed towards town when the accident happened. It was drizzling and the road was wet. Distance was kept from the car in front (SNL 5656H). However the first car in front (SNL 12006) did a sudden break which led to the first collision with the car in front (SNL 5656H) and I slowed ~~stop~~ down and jammed break as fast as I could but wasn't avoid the collision with SNL 5656H.


NB. Few minutes after the collision while we (all 3 car owners) were taking photos of the accident, two men in white stopped over and tried to offer advice and asked to send the car to their workshop where they will help to settle the insurance claim.

### Declaration

We declare the foregoing particulars are true in every respect.

 31/12/21  
Policyholder's Signature / Date & Time

—  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



# CERTIFICATE OF INSURANCE

## A AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TOH YING HUI ELAINE  
Period of Insurance : 18 Jul 2021 To 17 Jul 2022  
Engine No. : G4FGKH741973  
Chassis No. : KNAF3416MK5047586

Vehicle No. : SMM8843J  
Policy No. : 1900109936-01  
Endorsement No. :  
Issued Date : 17 Jun 2021

### ABOUT THE COVER

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Sum Insured : Market Value  
Off Peak Car : No  
First Year of Registration : 2019  
Insuring with COE/PAF : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
Mileage Condition : Unlimited Mileage

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

#### Section 2

Property Damage - \$0

Windscreen : \$100

#### Named Driver and Excess (where applicable)

TOH YING HUI (ZHUO YINGHUI) - \$600 (Own Damage), \$600 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
- 2.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- 3.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
- 4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622200

C&CKICP2 - ALTHAM

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

SSPDSD



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	378A
Vehicle No.:	SMM8843J
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	G4FGKH741973
Chassis No.:	KNAF3416MK5047586
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,460.00
Original Registration Date:	18 Jul 2019
First Registration Date:	18 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$14,460.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2029
PARF Rebate Amount:	\$10,845.00
COE Expiry Date:	17 Jul 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,009.00
COE Rebate Amount:	\$22,619.00
Total Rebate Amount:	\$33,464.00

The information contained herein is correct as at 03 Jan 2022

OK



# Kia Cerato 1.6A EX

Overview

Financial

Accessories

Similar

Research

Photos

Map

## CARRO

The Better Place to Buy Cars

**Price** **\$75,888**

**Depreciation** ⓘ \$9,330 /yr  
View models with similar depre

**Reg Date** 15-May-2019  
(7yrs 4mths 11days COE left)

**Mileage** 58,500 km (22.1k /yr)

**Manufactured** ⓘ 2018

**Road Tax** ⓘ \$738 /yr

**Transmission** Auto

**Dereg Value** ⓘ \$32,266 as of today (change)

**OMV** ⓘ \$14,389

**COE** ⓘ \$29,159

**ARF** ⓘ \$14,389

**Engine Cap** 1,591 cc

**Power** 93.8 kW (125 bhp)

**Curb Weight** ⓘ 1,287 kg

**No. of Owners** ⓘ 2