

ASS. REQ. BY:

REF: T11 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8200k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 09 days

Res.: Yes or No

Lum Sum: 1.34 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIX 6698 DYr Regn: 06, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyColour: N. Black

Sp. Reading: _____

Eng/No: _____

C/No: AG1430Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / A/Rlm orTyre Size: F: 235/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/12/21

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 3/1/2022

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Bottom Plat

Total/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Total/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Invs (\$ _____)

☐

: Weekend (\$ _____)

)

)

)

)

TOTAL

Report Format: _____

Imp Sum / I.B.I: (\$ _____)

1/3/22, 9:37 AM

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)
205 Braddell Road
Singapore 579701
Tel: 63838115 Fax: 62815767/65462533 Email: choojy@cdge.com.sg

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D20MFL0000326_01	Date of Loss:	30/12/2021
Vehicle Reg. No.:	SLX6698D	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		

Make/Model:	TOYOTA VELLFIRE, 2.5 Z G- EDITION CVT (A)	Vehicle Reg. Date:	28/06/2021
Vehicle Colour:	BLACK	Chassis No:	AGH300361271
Engine No:	2AR2594693		
Odometer:	5000 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4 days		

Not Insured
Return Repair

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS	Amount
Parts	2,941.61
Miscellaneous Items	11.00
Labour	1,320.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,272.61
+ GST 7.00% (S\$)	299.08
Nett Amount (S\$)	4,571.69

This claim is handled by: NGO TOH WEE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

.LS

MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2022)
M1-MPV	TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)
Repairer's	(Price-denominated Standard List)
Code: ComfortDelGro Engineering Pte Ltd/SLX6698D/03/01/2022 09:37	
These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

ates on Parts

Part No.	Particulars	%Disc	%Depr	Amount
	*RH FRT DOOR	25.00	0.00	*1,465.07 FL ✓
	*RH FRT DOOR TOP HINGE	25.00	0.00	*72.10 FL ✓
	*RH FRT DOOR BOTTOM HINGE	25.00	0.00	*72.10 FL ✓
	*RH FRT DOOR CHECKER	25.00	0.00	*186.58 FL ✓
	*RH FRT DOOR INNER TRIM BOARD	25.00	0.00	*2,126.30 FL X
Sub Total (\$\$)				3,922.15
- List Item Discount on L Items (\$\$)				980.54
Total Parts (\$\$)				2,941.61

ComfortDelGro Engineering Pte Ltd/SLX6698D/03/01/2022 09:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Repairer Estimates

on Miscellaneous Items

Particulars	Amount
<u>Miscellaneous Items</u>	
OD/TP Case (Insurer)	11.00
Sub Total (\$\$)	11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS RH FRT DOOR, RH FRT FENDER AND ETC	New	<i>400</i> 600.00
2	TO PUTTTY ABD RESPRAY ACCIDENT AREA SUCH AS RH FRT DOOR, RH FRT FENDER AND ETC	New	<i>500</i> 600.00
3	TO TRANSFER DOOR INNER PARTS FROM DAMAGE TO NEW DOOR	New	120.00
Gross Labour Cost (\$\$)			1,320.00

ComfortDelGro Engineering Pte Ltd/SLX6698D/03/01/2022 09:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >