

Immediate Advice

To: AXA Insurance Pte Ltd 24/1/2022

Survey Details:

Date of loss	31-Dec-21	
Date of appointment	3-Jan-22	
Date of survey	3-Jan-22	
Location of survey	TOH PAINTING & SERVICES PTE L	.TD

Vehicle Details:

Claim Type:	Third Part	y Claim	
Vehicle number	SNC 54351	P	
Make and Model	VOLKSWA	VOLKSWAGEN GOLF GTI 2.0L AT 5DR 5K19V3	
Date of registration	17/6/2010)	
Excess	-		
Market Value	\$	90,000.00	
Parf Rebate	\$	28,374.00	
Nett Loss	\$	61,626.00	

Repair details:

Initial Estimate \$ -

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>6</u>



Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$5,000.00 - \$6,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	