

(08/11/13) wef

ASS. REC. BY: Tom

REF:

C8/CT122000035/Riv43

Y08A

COR XP1RY: 2024/FEB

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 18880at Workshop m/s Watt Houghof 38, T0A W00N 10 E05T

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

30k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 24K

Veh No:

YN 18880Yr Regn: 2009 1F6B

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI PEP3BEc.c 2977

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

408536

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PE83BEA 11238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

7.00R16

R:

D/D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HEXUN

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

30/12/21

D.O.I.

06/01/22

Survey held at

Watt Hough

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

); S + RS, SI

☐

Interview (\$

); Photos

☐

Tech. Invs (\$

); Others

☐

Weekend (\$

);

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN1888D MITSUBISHI FUSO FE83

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Front panel <i>bt</i>		1636.00	
1	Center grille <i>CR</i>		599.00	
1	Center grille logo badge <i>RM</i>		85.00	
1	Center grille emblem "Fuso" <i>RM</i>		160.00	
1	Front bumper <i>bt</i>		986.00	
2	Front bumper side bracket LH/RH @2*\$205 ?		410.00	
1	Signal lamp RH <i>X</i>		211.00	
1	Tail gate sticker "Fuso" <i>RM</i>		180.00	
1	Aircon pipe H <i>bt</i>		380.00	
1	Aircon pipe L <i>bt</i>		380.00	
2	Front door RH/LH (Repair refer to labour) <i>Repair</i>		0.00	
1	Tail gate (Repair refer to labour) <i>Repair</i>		0.00	
			5027.00	
			-10% -502.70	
			4524.30	
<u>SPECIAL NETT ITEMS</u>				
1	Front car plate <i>bt</i>		35.00	
1	Rear tail gate sticker 60km/h <i>RM</i>		20.00	10
1	Rear tail gate sticker 22 Pax <i>RM</i>		20.00	10
1	Tail gat warning sticker <i>RM</i>		100.00	50
1	Rear step up metal assy <i>bt</i>		500.00	200
1	Rear step up metal assy warning sticker <i>RM</i>		100.00	50
2	Front door company decal RH/LH @2*\$25 <i>RM</i> <i>1pc</i>		50.00	25 25
2	Front door logo sticker RH/LH @2*\$100 <i>RM</i> <i>@50</i>		200.00	100
2	Front door warning sticker RH/LH @2*\$100 <i>RM</i> <i>@50</i>		200.00	100
1	Center grille clips <i>RM</i>		30.00	
1	Front bumper warning sticker <i>RM</i>		100.00	50
1	Front panel warning sticker <i>RM</i>		100.00	50
Total Parts			5979.30	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN1888D MITSUBISHI FUSO FE83

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1400.00 900
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To perform anti-rust treatment on affected areas	60.00	40
4	To remove and re-fix wiring system at accident damaged area and check all electrical & component for proper function	60.00 X	
5	Remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	120.00 80	
Labour Total :		3040.00	
TOTAL (PARTS & LABOUR):		9019.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
8 days
4/5
06/01/22 @ 1640
Resy after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/12/2021 11:15 (SGT)
Date of Accident	30/12/2021 15:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Along Jurong pier road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YN1888D

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SHENG WANG TRADING
Company Reg No	52825408A
Email Address	Operation@shengwang.com.sg
Mobile Phone No	(Phone) +65-88865238
Alternative Phone No	+65-88865238

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	FE83
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2500

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	5116622582-01
Cover Note Number	-

DRIVER

Name of Driver	MALAYAPPAN RAKKAMUTHU
Work Permit No	G8461422Q

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

10/05/1972
Indoor
14/01/2020
1 YEAR AND 11 MONTHS
Male
(Phone) +65-90869627
-
Operation@shengwang.com.sg
5C JALAN PAPAN
-
619420
No
Paid Driver
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
Weather Conditions Raining
Road Surface Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 3
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
Police Station Name Jurong West Neighbourhood Police Centre
Police Station Phone No (Phone) +65-18002689999
Alt. Police Station Phone No (Fax) +65-62672438
Police Station Address 700 Corporation Road Singapore 649818
Was notice of intended Prosecution given? No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

Refer to police report

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDV1889H
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car

Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBE4431M
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Commercial vehicle
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

31/12/2021

Reporting Centre Personnel's Signature
Name: STEVE
NRIC/FIN No.:

S990020



**SINGAPORE
POLICE FORCE**



T/20211230/2072

2 of 4

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20211230/2072

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YN1888D	Lorry	MITSUBISHI	FE83BE6SR DEA		Slightly Damaged	0


Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MUTHU	ID No.	NIL
Related Vehicle	GBE4431M (Lorry)	Contact No.	84528669
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MALAYAPPAN RAKKAMUTHU	ID No.	G8461422Q
Related Vehicle	YN1888D (Lorry)	Contact No.	90869627
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30/12/2021 at about 1518hrs, I was driving my vehicle (YN1888D) from Jurong Island toward Jurong Pier Road. After exiting from the Jurong Island Checkpoint, the traffic light indicated green light. Hence, I drove forward towards Jurong Pier Road.

While approaching Jurong Pier road, near 9A Jurong Pier Road, a vehicle (SDV1889H) suddenly applied e-brake due to the floods. I did not managed to stop on time and had collided on the rear of the front vehicle. Subsequently, I felt impacted from the rear. I was shock and did not alight from the vehicle immediately. As I come to my senses, I then alighted and noticed a lorry(GBE4431M) had collided on the rear of my vehicle. As I was about to approach to exchanged particular, the car driver had drove off after he had took photo of the accident. I had only managed to exchange particular with the rear driver. No visible injuries seen on the drivers. After exchanging of particular and take photos of the accident, we then left the area. No Police or Ambulance was called in.

SKETCH PLAN



JURONG PIER ROAD

A - YN 1888D

B - SDV 1889H

C - GBE 4431M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO GEARS

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

31/12/2021

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

STEVE
S990070

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

408A

Vehicle Details

Vehicle No.:

YN1888D

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2021

Vehicle Make:

MITSUBISHI

Vehicle Model:

FE83BE6SRDEA

Primary Colour:

White

Manufacturing Year:

2008

Engine No.:

4M42A70932

Chassis No.:

FE83BEA11238

Maximum Power Output:

-

Open Market Value:

\$33,161.00

Original Registration Date:

11 Feb 2009

First Registration Date:

11 Feb 2009

Transfer Count:

1

Actual ARF Paid:

\$1,659.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

10 Feb 2024

COE Category:

E - Open Category

COE Period(Years):

5

PQP Paid:

\$13,688.00

COE Rebate Amount:

\$5,782.00

Total Rebate Amount:

\$5,782.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 31 Dec 2021

OK

Mitsubishi Fuso Canter FE83 (COE till 02/2029)

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**OUR AWARDS**

Price	\$58,800	Lifespan ?	22-Feb-2029
Depreciation ?	\$8,240 /yr	Reg Date	23-Feb-2009 (7yrs 1mth 16days COE left)
Mileage	N.A.	Manufactured ?	2008
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$19,531 as of today (change)	Fuel Type	Diesel
COE ?	\$27,376	OMV ?	\$33,486
Engine Cap	2,977 cc	ARF ?	\$1,675
Curb Weight ?	2,420 kg	No. of Owners ?	2