



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22000085/Rtf3n2	Date: 07/03/2022
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKM 184D	Veh. Inspected	SMQ 7883D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10013232/JM	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	04/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W 216I GRAN TOURER	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WBA6V120805P16952	Colour	WHITE	
Odometer	22623 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	PIRELLI	6 mm	
L/H Front Tyre	205/60 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/60 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/60 R16	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/01/2022	Inspection Date	06/01/2022	
Survey held at	BIS AUTOMOBILES PTE LTD 30 TEBAN GARDENS CRESCENT, SINGAPORE 608927			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		