

ASS. REC. BY: Taught

REF:

CS3/1419 22000086/Tivf3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SMQ 4022SPolicy No. 1900246059Claims No. 0510623475SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$12K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBS5758R Yr Regn: 2021 / June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha MX King c.c 150Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3460750MK094 934Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NP / S/Rim / STD A/Rim orTyre Size: F: 60/80R17R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS.

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 25/12/21 D.O.I. 4/1/22 @ 320pmSurvey held at One MotorDes. of Damages: Fr Rear / O/S / (N/S) U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No 619

6/1/22 Submit DAR

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 6/1/22-typist

Rep. Format: _____

Lump Sum / I.B.L. (\$) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

10) Damaged (30) Stuffed (99) Included (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ROR MOTORCYCLE

4. Hot Ch. Item (R)

Motorcycle

Vehicle No: **FBS5758R.**

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate	bt	✓	
3002	995065	Front Tyre	?		
3003	995095	Front Rim	con	✓	
3004	994872	Front Tyre Rim Spoke shaft	?		
3005	991771	Front Fender Wheel Guard	cut	✓	
3006	991283	Front Brake Disc	?		
3007	991281	Front Brake Caliper			
3008	991785	Front Fork Assy	bt	✓	
3009	991787	Front Fork Inner Tube			
3010	991789	Front Fork Outer Tube			
3011	991167	Front Fork Bracket	bt	✓	
3012	991182	Front Fork Oil Seal			
3013	991174	Front Fork Garnish			
3014	992376	Front Headlamp Rim Cowling	cut	✓	
3015	992328	Front Headlamp	?		
3016	992337	Front Headlamp Bracket			
3017	992345	Front Headlamp Fairing			
3018	992130	Front Windshield			
3019	992134	Front Wing Mirror	con	✓	
3020	995245	Front LH Signal Lamp	con	✓	
3021	995246	Front RH Signal Lamp	?		
3022	992556	Meter Casing			
3023	992553	Front top fairing light LH	cut	✓	
3024	991019	ERP Bracket			
3025	991020	ERP Unit			
3026	992446	Ignition Switch			
3027	992442	Ignition Key Assy			
3028	990706	Cowling Stay			
3029	994470	Steering Stem			
3030	994427	Steering Cone & bearing	con	✓	
3031	992299	Handle Bar	bt	✓	
3032	992312	Handle Bar Switch			
3033	992310	Handle Bar Grip	mis	✓	
3034	995184	Handle Bar Balancer LH	cut	✓	
3035	992300	Handle Bar Balancer RH			
3036	992179	Fuel Tank			
3037	990438	Brake Reservoir			
3038	990621	Clutch Lever	cut	✓	
3039	992293	Hand Brake Lever			
3040	991119	Side Fairing	dis	✓	2
3041	994220	Side Fairing Top Garnish	cut	✓	
3042	994219	Side Fairing lower	cut	✓	
3043	991118	Fairing Shield			
3044	992047	Front Top Fairing Inner Garnish			
3045	991123	Fairing Top Garnish			
3046	990538	Center Fairing Front	cut	✓	
3047	993378	Rear Fairing	?		
3048	991121	Fairing Stopper			
3049	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
3050	995074	Radiator	bt	✓	
3051	992738	Radiator Cowling			
3052	994146	Seal Assy			
3053	990915	Engine Crash Bar			
3054	990928	Engine Guard			
3055	990219	Battery			
3056	990224	Battery Cover			
3057	990223	Battery Bracket			
3058	991144	Foot Brake			
3059	991154	Front Foot Rest	cut	✓	
3060	991779	Front Foot Rest Bracket			
3061	994269	Side Stand			
3062	992549	Main Stand			
3063	990615	Clutch Engine Cover			
3064	992478	Kick Starter Rubber			
3065	992477	Kick Starter Lever			
3066	991145	Foot Gear Shifter	bt	✓	
3067	993500	Rear Foot Rest	cut	✓	
3068	993501	Rear Foot Rest Bracket			
3069	992581	Exhaust Muffler Heat Shield			
3070	991058	Exhaust Muffler Assy			
3071	993719	Rear LH Shock Absorber			
3072	993720	Rear RH Shock Absorber			
3073	995065	Rear Tyre			
3074	991200	Rear Rim			
3075	994872	Rear Tyre Rim Spoke			
3076	993474	Rear Fender Wheel Guard			
3077	993443	Rear Fender Mudflap			
3078	992940	Rear Brake Disc			
3079	992936	Rear Brake Caliper			
3080	995236	Rear Spocket			
3081	990585	Chain			
3082	990580	Chain Guard			
3083	994530	Swing Arm			
3084	993819	Rear Sub frame			
3085	995245	Rear LH Signal Lamp			
3086	995246	Rear RH Signal Lamp			
3087	995251	Rear Taillamp			
3088	993626	Rear Number Plate			
3089	994192	Side Box			
3090	992927	Rear Box	?		
3091	992928	Rear Box Bracket			
3092	991328	Emblem			
3093	990247	Sticker set	con	✓	

No of Items: _____ Assessor: _____

05 days