

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/01/2022 12:09 (SGT)
Date of Accident 31/12/2021 19:35 (SGT)
Exact Location of Accident Singapore
Additional Location Information LOR 2 TOA PAYOH
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJT8522J

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner CHUNG TUCK KWAI
NRIC No S1232375A
Email Address csameric@hotmail.com
Mobile Phone No (Phone) +65-96345297
Alternative Phone No +65-96345297

VEHICLE PARTICULARS

Manufacturer Nissan
Model Sylphy
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only
Vehicle Category Private car
Transmission Auto
CC 1600

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1800156762
Cover Note Number -

DRIVER

Name of Driver CHUNG TUCK KWAI
NRIC No S1232375A

Date Of Birth	03/11/1957
Occupation	Indoor
Date Of Driving Pass	11/01/2000
Driving experience	21 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96345297
Alt. Phone Number	+65-96345297
Email Address	csameric@hotmail.com
Address	159 YISHUN STREET 11 #05-174
Address complement	-
Postcode	760159
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	TAY BI HUA
Gender	Female

PASSENGER 2

Name	CHUNG WAN XIN
Gender	Female

PASSENGER 3

Name	GARLAND MAK
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMR7063Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	YAK BOON TECK
Contact Number	(Phone) +65-97776878
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3

SKETCH PLAN

IMPORTANT NOTICE

Vehicle No: _____

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repealate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and the copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: _____

 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: _____


 Reporting Centre Person's Signature
 Name: _____
 #RIC/P111 No: _____

On Friday 31st December 2021 at around 7.35pm, I (CHUNG TUCK KWAI, NRIC S1232375A) male driver of Nissan Sylphy saloon car (Vehicle Registration No. SJT8522J) was driving along slip road from Lorong 2 Toa Payoh adjoining Pan Island Expressway (PIE) towards Changi Airport, behind a Honda Vezel saloon car (Vehicle Registration No. SMR 7063Z), driven by male driver (YAK BOON TECK, NRIC No. S7206072E).

The driver of Honda had stopped at the end of the slip road that adjoins the side parallel road of PIE, so I followed suit and stopped behind.

At the next moment, driver of Honda gradually accelerates to move into the side parallel road and seeing this movement, I proceeded to gradually accelerate to move up a bit.

After reviewing that an oncoming vehicle from the right side, travelling along the side parallel road, was very far away, I decided to proceed to filter into that road.

However as I was just about to move forward, I glanced left and was shocked to realise that the driver of the Honda vehicle had stopped abruptly after turning into the side parallel road. I immediately applied emergency braking but was only able to reduce the impact to a light bump to the rear bumper of the Honda vehicle, most probably due to the fact that my vehicle had just moved from a stationary position.

After this minor collision, the driver of the Honda vehicle immediately but slowly turned to stop his vehicle to the left side of the parallel road, to access the damage and also to ensure safety from any oncoming traffic.

I also had to follow suit behind him in order not to cause traffic congestion to other vehicles behind me.

We both reviewed the damages of each vehicle and exchanged mobile contact numbers. Driver of the Honda vehicle mentioned that he stopped abruptly because he had judged that a supposedly oncoming vehicle may be too near. He had mentioned he had other passengers in his vehicle, to which I had enquired about their well-being and heard his reply that they are okay. From that point both parties agree to make respective traffic accident reports and to keep contact going forward.

Additional Information as at when and after Time of Accident::

Damage to Honda Vehicle: Dent and scratches to center of rear bumper. Vehicle still functional. Vehicle was mentioned as covered by NTUC Insurers

Damage to Nissan Vehicle: Slight damage to Front Number Plate and minor scratches on small area on Left side of Front bumper. Vehicle still functional. Vehicle covered by AIG insurers.


Weather: Slight drizzle just after earlier heavy downpours

Road Conditions: Extremely Wet due to earlier heavy downpours

No injuries to both drivers and passengers of both vehicles

1/2/22, 10:51 PM

Google Maps



<https://www.google.com.sg/maps/@1.3299289,103.846689,19.82z>



















