



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM22000093/Avy3e2 Date: 17/03/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 1151Y	Veh. Inspected	SGX 6628R	
Policy No.	GA571552/1	Coverage (\$)	0.00	
Claim No.	S2M03Q0T	Excess (\$)	0.00	
Assign From	KHONG LYNN	Assign Date	04/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2130422A069556	Colour	SILVER	
Odometer	59813 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	6 mm	
L/H Front Tyre	225/55 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/01/2022	Inspection Date	10/01/2022	
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	