

TPAXA.
Veron

SGX6628R 2017 Nov

Mercedes Benz E200 1991cc

WTD2130422A069556

Front Number Plate	Det'd	30(SN)	/
Front Number Plate Holder	Det'd	30(SN)	/
Front Number Plate Garnish.	Det'd	103	/
Front Bumper	Det'd	1516	/
Front Bumper Lips	new	50(SN)	/
Front Bumper Side Holder x 02	new	105 x 2 = 210.	x
Front Bumper Reinforcement.	new	689	x.
Front Bumper Sponge	new	183	/
Front Bumper Lower Grille.	new	201	x
Front Bumper Side Grille x 02	new	72 x 2 = 144.	72.
Front Bumper Sensor x 04	new	245	x
Front Bumper Inner Top Cover	new	242	/

SGX6628R.

Front Bumper lower Garnish.	Behind	394	/
Front Grille.	crushed	.895	/
Front Grille Logo.	cut	112	/
Front Grille clips	new	20(SN)	/
Front Grille outer Chrome.	crushed	288	/
Hendcap LH.	crushed	3125	/
Bonnet	Pyris	2092	X.
Bonnet Logo	new	86	/
Front LH Fender	Pyris	1042	X

7261

S.N: 130

6534.50

SG x 6628R.

Panel Beating

~~1000~~ 500

Spray Painting

~~1000~~ 600

Wiring

~~1000~~ 30

To remove front bumper sensor

~~1000~~ 60 1340

To perform diagnostic test.

~~2000~~ 150

14,832.00

total: 8004.90

H/s: G.H.K.

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: