



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000124/Atf3n2	
			Date: 26/04/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SDW 8178A	Veh. Inspected	SKB 4853M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200011/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN SCIROCCO	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WVWZZZ13ZBV009584	Colour	GREY
	Odometer	126608 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/35 R19	FALKEN	6 mm
	L/H Front Tyre	255/35 R19	FALKEN	6 mm
	R/H Rear Tyre	255/35 R19	FALKEN	6 mm
	L/H Rear Tyre	255/35 R19	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/12/2021	Inspection Date	05/01/2022
	Survey held at	SR AUTOWORKS PTE LTD 8 KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	