


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident took place on 22 OCT (PM) at about 6:16pm, along the small road exit to Jln Jurong Kechil.

while my vehicle, SLG 7774, was stationarily waiting for the red light to turn green, suddenly vehicle SJL 8668P knocked into the back of my vehicle. The heavy impact caused the back of the vehicle badly dented.

There are vehicle camera (Front + back) as proof.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a **Fourteen (14) days clause** whereby the claim must be made within the stipulated timeframe from the day of occurrence.

☒	Reporting Only
☐	Claim OD
☐	Claim TP
☐	Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:
28 OCT 2021, 11:57pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Rakeshwar Arne
NRIC/FIN No.:























