

(08/11/13) wef

ASS. REC. BY: Rahul

REF:

CS/HLA 22000 ISS/RIVY3

4360

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY


To Inspect Vehicle No: SLZ 1418Tat Workshop m/s BORNEO MOTORof 2, PANDAN CRESCENTInsured: HLAPolicy No. MP316928Claims No. MPC03069Sum Insured: TDA Excess: 700

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 63K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

REPAIR LIMIT - 27K

28/2/22 Rasul informed final fig \$9492.60 (Red 9615.80, 50%)

Veh No:

SLZ 1418TYr Regn: 2018 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA VIOS 6 AWDc.c 1496

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

55901

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR2B23F3901109906

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/01/22

D.O.I.

02/01/22

Survey held at

BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 28/2/22-typist

Days Of Repair: 7Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

); \$ + RS \$

☐

Interview (\$

); Photos

☐

Tech. Invs (\$

); Others

☐

Weekend (\$

);

Report Format: Merimen

Lump Sum / I.B.I: (\$9492.60)



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
HL Assurance Pte Ltd 11 Keppel Road #11-01 Abi Plaza Singapore 089057			S1000028 / ICHLA		Mr Yong Chor Chim 238 Bishan Street 22 #12-220 Singapore 570238 Mobile: 98340572		
			Document No. 0				
			Document Date 04/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	24/04/2018	SLZ1418T	0	12455	72/OD/SLZ1418T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B23F3901109906		2NRX258512	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MP316928 ACC DATE:02.01.2022 DRIVE IN:03.01.2022 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100 200.00	
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				180.00	
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40	
5	B	BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID.				540.00	
6	B	BP-LAB2 R/I REAR REVERSE CAMERA TO FAC REPAIR. REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				360 720.00	
7	B	BP-LAB2 R/I REAR WINDSCREEN GLASS TO FAC REPAIR.				X 462.00	
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00	
9	L	BP-LPO SUPPLY REGN PLATE (PO#)				X 80.00	
10	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				2880	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
HL Assurance Pte Ltd 11 Keppel Road #11-01 Abi Plaza Singapore 089057		S1000028 / ICHLA	Mr Yong Chor Chim 238 Bishan Street 22 #12-220 Singapore 570238	
		Document No. 0	Mobile: 98340572	
		Document Date 04/01/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	24/04/2018	SLZ1418T	0	12455	72/OD/SLZ1418T

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3901109906	2NRX258512	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 RESPRAY ACC AFFECTED AREAS @590 X 5				2950 3840.00
12	1	SPC507-0D015 11 BACK SENSOR 040 SUPER WHITE ?	1.00	197.80		197.80
13	2	S52159-0U963 COVER, RR BUMPER L/C	1.00	557.70		557.70
14	3	S52161-0K040 PIECE, RR BUMPER re	10.00	4.30		43.00
15	4	S52462-0D020 PAD, RR BUMPER, RH re	2.00	11.70		23.40
16	5	S75895-0D270 TAPE, MOULDING, NO.1 re	2.00	53.50		107.00
17	6	S52575-0D340 RETAINER, RR BUMPER ?	1.00	164.30		164.30
18	7	S52576-0D330 RETAINER, RR BUMPER ?	1.00	164.30		164.30
19	8	S52023-0D090 REINFORCEMENT SUB-AS ?	1.00	353.10		353.10
20	9	S81910-0D050 REFLECTOR ASSY, REFL ?	1.00	99.80		99.80
21	0	S81920-0D050 REFLECTOR ASSY, REFL ?	1.00	99.80		99.80
22	1	S58307-0D480 PANEL SUB-ASSY, BODY repair photo	1.00	786.30		786.30
23	2	S61601-0D260 PANEL SUB-ASSY, QUAR repair	1.00	963.70		963.70
24	3	S61063-0D090 TROUGH SUB-ASSY, LUG ?	1.00	128.20		128.20
25	4	T08826-08115 PANEL BONDING ADX	1.00	267.20		267.20
26	5	S64401-0D360 PANEL SUB-ASSY, LUGG bt	1.00	838.90		838.90
27	6	S64461-0D180 WEATHERSTRIP, LUGGAG ?	1.00	186.50		186.50
28	7	S64503-0D090 ARM SUB-ASSY, LUG CO ?	2.00	69.70		139.40
29	8	S64600-0D040 LOCK ASSY, LUGGAGE C ?	1.00	423.90		423.90
30	9	S58387-0D200 PLATE, RR FLOOR FINI ?	1.00	295.40		295.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
HL Assurance Pte Ltd 11 Keppel Road #11-01 Abi Plaza Singapore 089057			S1000028 / ICHLA		Mr Yong Chor Chim 238 Bishan Street 22 #12-220 Singapore 570238 Mobile: 98340572			
			Document No. 0					
			Document Date 04/01/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	NSP151R	AEXRKT E1	24/04/2018	SLZ1418T	0	12455	72/OD/SLZ1418T	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3901109906		2NRX258512	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
31	0	T90467-08186 C3 CLIP <i>na</i>			2.00	2.60		5.20
32	1	S75431-02090 LUGGAGE COMP EMBLEM, <i>na</i>			1.00	65.30		65.30
33	2	S75442-0D400 PLATE, LUGGAGE COMPT <i>na</i>			1.00	48.30		48.30
34	3	S75444-0D690 PLATE, LUGGAGE COMPT <i>na</i>			1.00	37.60		37.60
35	4	S81550-0DA50 LAMP ASSY, RR COMBIN <i>na</i>			1.00	403.80		403.80
36	5	S81560-0DA50 LAMP ASSY, RR COMBIN <i>na</i>			1.00	403.80		403.80
37	6	S52562-0D130 RETAINER, RR BUMPER, <i>na</i>			1.00	63.40		63.40
38	7	S52563-0D130 RETAINER, RR BUMPER, <i>na</i>			1.00	63.40		63.40
39	8	S81580-0D500 LAMP ASSY, RR, RH <i>na</i>			1.00	260.60		260.60
40	9	S81590-0D500 LAMP ASSY, RR, LH <i>na</i>			1.00	260.60		260.60
41	0	T89997-30100 ANTENNA, ELECTRICAL <i>na</i>			1.00	76.30		76.30
42	1	T21000-20 SIKI 182010 SIKI TACK GO! (BLA <i>na</i>			2.00	108.00		216.00
43	2	T21000-22 SIKI 207. G+P ADHESIVE PRIMER <i>na</i>			1.00	200.00		200.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and Is subject to final approval from Insurance Company <i>Handwritten notes:</i> <i>7 days</i> <i>EXCESS: TBA</i> <i>07/01/22</i> <i>Repay before paid</i>								
For & on behalf of Borneo Motors (Singapore) Pte Ltd					Customer's Signature		Charge Summary	
Signature: _____					Please acknowledge receipt of vehicle		Total 19,108.40	
Date: _____							GST 7.00% 1,337.59	
					Parts 7,944.00		Less 0.00	
					Labour 10,904.40			
					Sublet 260.00			
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 20,445.99	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/01/2022 19:10 (SGT)
Date of Accident	02/01/2022 10:00 (SGT)
Exact Location of Accident	Ang Mo Kio Ave 1, Singapore
Additional Location Information	Ang Mo Kio Ave 1 heading CTE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1418T
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Yong Chor Chim
NRIC No	S1145436D
Email Address	ccyongmedeus@hotmail.com
Mobile Phone No	(Phone) +65-98340572
Alternative Phone No	(Home) +65-98340572

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MP316928
Cover Note Number	-

DRIVER

Name of Driver	Yong Chor Chim
NRIC No	S1145436D

Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Date Of Birth	17/10/1955
Occupation	Outdoor
Date Of Driving Pass	14/01/1983
Driving experience	39 YEARS
Gender	Male
Mobile Number	(Phone) +65-98340572
Alt. Phone Number	(Home) +65-98340572
Email Address	ccyongmedeus@hotmail.com
Address	BLk 238 #12-220 Bishan Street 22
Address complement	-
Postcode	570238
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Describe Circumstances of the Accident

I was driving along Ang Mo Kio Avenue 1 towards the direction for CTE.

It was raining heavily and visibility is poor. My car (SLZ1418T) was hit at the rear side (right) by a VAN (unknown).

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	436D
Vehicle No.:	SLZ1418T
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E (AUTO)
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	2NRX258512
Chassis No.:	MR2B23F3901109906
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,707.00
Original Registration Date:	24 Apr 2018
First Registration Date:	24 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$13,707.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2028
PARF Rebate Amount:	\$10,280.00
COE Expiry Date:	23 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,000.00
COE Rebate Amount:	\$25,166.00
Total Rebate Amount:	\$35,446.00

The information contained herein is correct as at 08 Jan 2022

OK

Toyota Vios 1.5A E

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$61,600		
Depreciation 	\$9,080 /yr View models with similar depre	Reg Date	15-Jan-2018 (6yrs 6days COE left)
Mileage	29,000 km (7.3k /yr)	Manufactured 	2017
Road Tax 	\$682 /yr	Transmission	Auto
Dereg Value 	\$33,400 as of today (change)	OMV 	\$13,876
COE 	\$38,200	ARF 	\$13,876
Engine Cap	1,496 cc	Power	79.0 kW (105 bhp)
Curb Weight 	1,085 kg	No. of Owners 	1
Type of Vehicle	Mid-Sized Sedan		