

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD		Ref:	CS/ASM22000162/Rqy3e2
	8 SHENTON WAY AXA TOWERSING			Date:	22/03/2022
	ATTN: LEONG JAC	CQUELINE		Code:	ASM
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 6388L	Veh. Inspected		SLN 5055T
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M03PYT	Excess (\$)		0.00
	Assign From	LEONG JACQUELINE	Assign Date		05/01/2022
2. Vehicle Particulars & Condition					
	Make & Model	CHEVROLET ORLANDO 1.4AT	c.c		1362
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	KL1YA7589HK610757	Colour		GREY
	Odometer	64403 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA		6 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA		6 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA		6 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	31/12/2021	Inspection Date	е	18/01/2022
	Survey held at	EM SOLUTION PTE LTD	-		
		160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•				