ASS. REC. BY: STEVE REF: CS3/ASM	770001661 43
- V	
PNS	Veh No: SJT 767 Y Yr Regn: 29/9/09
From: Date:	Veh No: Yr Regn: Yr Till Y
Estimated Cost:	Type: M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD (AP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or
To Inspect Vehicle No:	Make: Tayota VIOS co 1497
at Workshop m/s	Colour Red A/C: Insured / Std / NI / NA
of	Sp.Reading 138567 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: MR053 HY9305173154
Claims No. S1M03PLL	Gen. Cond: Good / Fall / Poor / Burnt
Sum Insured: Excess:	Steering: Inforder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inferder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / SRIM / STD A/RIM or
	Tyre Size: F: 185 (60) 15
(Policy Condition)	R:
Remark: The veh had commenced its · N/S O/S	BS (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. U mm L/Bal. U mm
Est. Repairs; 5 days Res.: Yes or No	D.O.A. 77 12 97
av 3 Val · Yes or No	Survey held at Empire Image
Lunioung	Des. of Damages : Frt Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
A district Added Unstruction	Land Of Ok 31
Date / Time Action / Instruction RCDG7	
5 report days	
27/01/22@10.22am revised to Cynthia Loh via Smart Claims.	
27/01/22 Submit PRS.	
	Dave Of Repair: 5
Date/Time, File Pass to? : Prell. Report	Days Of Repair: 5 Resurvey No. of Trip: 2 Survey Fee:
27/01 Typist : Final Report	Transportation:
Date/Time, File Return to? Add Fe	: Site Insp (\$)s+RSSi
2)	: Interview (\$) Photos
Report Format: SMART CLAIMS - PRS	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$)	:Weekend (\$)
	TOTAL