

Certification for Bus Repairs

SBS Transit

CBR REF NO. : AM20220052

Depot : AM

Report No.: E00292022

BUS VEHICLE NO. : SBS3128Y

Driver's Co no. & Name : 79348 Chin Wai Loon

Accident Date : 30/12/2021

Date in : 30/12/2021

Date Out : 24/01/2022

Yr Of Reg	Make / Model	Chassis No.
2012	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P925CA155931

Stock Code	Description	Quantity	Total Material cost (S\$)
		0	\$0.00
30750294	BATTERY ACCESS PANEL;SHEETMETAL ✓ DIS	1	\$639.00
30750003	SEALED LEVER LATCH;OS/NS;RR SIDE DR ✓ NEC	1	\$34.00
N200LMF	SEMI MAINT.FREE BATTERY 200AH;FURUKAWA ✓ DM	1	\$195.00
N200LMF	SEMI MAINT.FREE BATTERY 200AH;FURUKAWA ✓ DM	1	\$195.00
42541861	PRESSURE SWITCH;0.8 / 0.15BAR	1	\$89.00
42541861	BATTERY BOX;B9TL EU5 ✓ CRA	1	\$897.00
42541861	PRESSURE SWITCH;0.8 / 0.15BAR	-1	(\$89.00)
TOTAL FOR PARTS			S\$ 1960.00 ✓
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	184.00 X NN
2	Contractor's repair charges	S\$	780.00 ✓
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST		S\$	964.00 ✓
Repair cost of Advertisement / Livery		S\$	97.50 ✓
TOTAL DAMAGE		S\$	3021.50

Certification for Bus Repairs

SBS TransitCBR REF NO. : AM20220052Depot : AMReport No.: E00292022BUS VEHICLE NO. : SBS3128YDriver's Co no. & Name : 79348 Chin Wai LoonAccident Date : 30/12/2021Date in : 30/12/2021Date Out : 24/01/2022

Yr Of Reg	Make / Model	Chassis No.
2012	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P925CA155931
TOTAL DAMAGE		S\$ 3021.50
Overheads		S\$ 877.20
Towing Charges		S\$ 218.00
Loss of Use		S\$ 833.60
TOTAL LOSS		S\$ 4950.30

X NN

✓

3055.5

2 Days

Prepared By : Li MingDate : 08/02/2022

Approved By

Workshop Mgr : Zhannie Tan Zhan HongDate : 08/02/2022

Survey Fee	refer to Group Claims
TOTAL DUE	S\$ 4950.30

Acknowledged By

Depot Safety : Chang Su PengDate : 11/02/2022

* This is computer generated document and does not require signature

LKK Auto Consultants hence notify the Repairer of the following:

- To re-survey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: