



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22000177/Apa3q2 Date: 08/11/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 8758C	Veh. Inspected	SMU 9774B	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M03PZG	Excess (\$)	0.00	
Assign From		Assign Date	05/01/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A1	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WAUZZZGB8LR044561	Colour	WHITE	
Odometer	16094 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	215/45 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/45 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/45 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/01/2022	Inspection Date	05/01/2022	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	