## Company & GST Registration No. 200616038C

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sq

Our Ref:

**SMU 9774 B** 

Your ref:

SH 8758 C

04 January 2022

## **AXA INSURANCE PTE LTD**

8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: OH HUI CHIN **VEHICLE NUMBER: SMU 9774 B** 

YOUR INSURED VEHICLE NUMBER: SH 8758 C

ACCIDENT ON 03 Jan 2022 ALONG PICKERING ST TWDS CHURCH ST AT CHINA ST JUNC

AT ABOUT 10:35 HOURS

We refer to your email/fax dated 04 Jan 2022 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

## N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



(Name & Signature):

inspection. Thank you! Appointed surveyor:

FOR SURVEYOR:

Date & Time of Inspection:

Please initial here after completion of pre-repair

N-51 AUTOMOTIVE PTE LTD