

(08/11/13) wef

ASS. REC. BY:

REF:

CS/CT122000184/R1943

C
2014

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 47677at Workshop m/s BORNGOof PANDAN RDInsured: CTI

Policy No. _____

Claims No. SNM22D200106/C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: SSK

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 47677 Yr Regn: 2017 / JunType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA VIOS 1.5E CVT c.c. 1496Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 323031 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHFB29F390201936Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/50R16
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>04/01/22</u>	D.O.I.	<u>06/01/22</u>

Survey held at BORNGO MOTORDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 21K

25/02/22@2.55pm revised to Irene Tay via Merimen.

We will be advising our Principal a cost of repair of L/S \$7,859.10/- with 5 days of repair,
subject to their approval. (Red \$9361, 54%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 25/02 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format: MER-TPLump Sum / I.B.I.: (\$ 7859.10)

chcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 04/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	07/06/2017	SLP4767T	0	12463	75/DS/SLP4767T
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3902011936		2NRX159042	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:PC821S ACC DATE:04/01/2022 DRIVE IN:04/01/2022 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30	100.00
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST					180.00
3	B	BP-LAB2 RESET ECU UPON COMPLETION OF REPAIR					180.00
4	L	BP-LPO SUPPLY REGN PLATE (PO#)					80.00
5	B	BP-LAB2 REPL ACC AFF AREA					5040.00
6	B	BP-RES2 RESPRAY ACC AFF AREA					3540.00
7	1	K52119-0U920 COVER, FR BUMPER, L	1.00	525.80			525.80
8	2	K53112-0D360 GRILLE, RADIATOR, LW	1.00	304.70			304.70
9	3	K52021-0D140 REINFORCEMENT SUB-AS?	1.00	423.90			423.90
10	4	K52127-0D430 COVER, FR BUMPER HOL	1.00	63.40			63.40
11	5	K53101-0D904 GRILLE SUB-ASSY, RAD	1.00	216.60			216.60
12	6	K53121-0D200 MOULDING, RADIATOR G	1.00	73.40			73.40
13	7	K53124-0D140 MOULDING, RADIATOR G	1.00	73.40			73.40
14	8	K53301-0D160 HOOD SUB-ASSY	1.00	982.10			982.10
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
				Document No.					
				0					
				Document Date					
				04/01/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	NSP151R	CEXRKT Q1	07/06/2017	SLP4767T	0	12463	75/DS/SLP4767T		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MHFB29F3902011936		2NRX159042	60	Ng Mei Yen	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
15	9	K53866-0D160 SEAL, FR FENDER TO C ?			1.00	48.60		48.60	
16	0	K53867-0D160 SEAL, FR FENDER TO C ?			1.00	48.60		48.60	
17	1	K90105-T0120 BOLT, FLANGE ?			1.00	2.50		2.50	
18	2	K53811-K0020 PANEL, FR FENDER, RH repair			1.00	747.70		747.70	
19	3	K53812-K0020 PANEL, FR FENDER, LH repair			1.00	747.70		747.70	
20	4	K16400-0Y231 RADIATOR ASSY X			1.00	2176.50		2176.50	
21	5	K16711-0Y090 SHROUD, FAN X			1.00	314.90		314.90	
22	6	K81110-0D831 HEADLAMP ASSY, RH scd			1.00	644.20		644.20	
23	7	K81150-0D831 HEADLAMP ASSY, LH scd			1.00	644.20		644.20	
24	8	K90975-T2008 EMBLEM, SYMBOL			1.00	61.90		61.90	
<div style="border: 1px solid black; padding: 5px;"> <p>UKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> </div>					<p><i>Resul</i> <i>Hp 90010068</i> <i>5 days</i> <i>06/01/22 @ 1200</i> <i>Resy before paint</i> <i>email: resul@ukkauto.com</i></p>				
For & on behalf of		Customer's Signature			Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd							17,220.10		
		Please acknowledge receipt of vehicle			Parts		GST 7.00%		
					Labour		1,205.41		
					Sublet		Less		
					Lubrication/Fluid		0.00		
					Others		Amount Due		
							18,425.51		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/01/2022 20:47 (SGT)
Date of Accident	04/01/2022 12:05 (SGT)
Exact Location of Accident	Duxton Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP4767T
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	GRAB RENTALS PTE LTD
Company Reg No	2XXXXX200G
Email Address	gr.sg.accident@grab.com
Mobile Phone No	(Phone) +65-98754612
Alternative Phone No	(Office) +65-66550005

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	G 400001194 MCX
Cover Note Number	-

DRIVER

Name of Driver	TAHIR BIN MOHAMED YAHYA
NRIC No	SXXXX582Z

Date Of Birth 22/08/1977
 Occupation Outdoor
 Date Of Driving Pass 26/07/2004
 Driving experience 17 YEARS AND 6 MONTHS
 Gender Male
 Mobile Number (Phone) +65-98754612
 Alt. Phone Number -
 Email Address gr.sg.accident@grab.com
 Address BLK 8 TECK WHYE AVENUE #09-81
 Address complement -
 Postcode 680008
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name UNKNOWN
 Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON THE 04/01/2022 AT ABOUT 1205 HOURS, I WAS DRIVING VEHICLE A (SLP4767T) ALONG DUXTON ROAD ON A ONE WAY STREET WHEN SUDDENLY VEHICLE B (PC821S) FAILED TO CONFORM TO HIS STOP LINE COMING FROM DUXTON HILL, CROSSED TO THE FRONT OF MY PATH AND I HIT HEAD ON AGAINST HIS LEFT SIDE. NOBODY WAS INJURED.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC821S
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	(Phone) +65-90305454
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE


- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON THE 04/01/2022 AT ABOUT 1205 HOURS, I WAS DRIVING VEHICLE A (SLP4767T) ALONG DUXTON ROAD ON A ONE WAY STREET WHEN SUDDENLY VEHICLE B (PC821S) FAILED TO CONFORM TO HIS STOP LINE COMING FROM DUXTON HILL, CROSSED TO THE FRONT OF MY PATH AND I HIT HEAD ON AGAINST HIS LEFT SIDE. NOBODY WAS INJURED.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

04/01/22 1320

Witnessed by Reporting Centre
Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SLP4767T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jan 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2NRX159042
Chassis No.:	MHFB29F3902011936
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,785.00
Original Registration Date:	07 Jun 2017
First Registration Date:	07 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$7,785.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2027
PARF Rebate Amount:	\$5,838.00
COE Expiry Date:	06 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$27,950.00
Total Rebate Amount:	\$33,788.00

The information contained herein is correct as at 06 Jan 2022

OK

Toyota Vios 1.5A E

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price	\$55,800		
Depreciation	\$9,580 /yr View models with similar depre	Reg Date	07-Jun-2017 (5yrs 5mths COE left)
Mileage	60,000 km (13.1k /yr)	Manufactured	2017
Road Tax	\$682 /yr	Transmission	Auto
Dereg Value	\$33,788 as of today (change)	OMV	\$12,785
COE	\$51,600	ARF	\$7,785
Engine Cap	1,496 cc	Power	79.0 kW (105 bhp)
Curb Weight	1,065 kg	No. of Owners	2