

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/11/2021 13:32 (SGT)
Date of Accident 09/11/2021 18:20 (SGT)
Exact Location of Accident PIE, Singapore
Additional Location Information PIE TOWARDS CHANGI
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMW9881P

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LOKE WEE CHOONG
NRIC No SXXXX300C
Email Address CWCONS_LOKE@YAHOO.COM.SG
Mobile Phone No (Phone) +65-93829639
Alternative Phone No +65-93829639

VEHICLE PARTICULARS

Manufacturer Toyota
Model ALTIS
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1798

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 2070171431
Cover Note Number -

DRIVER

Name of Driver LOKE WEE CHOONG
NRIC No SXXXX300C

Date Of Birth	13/07/1973
Occupation	Outdoor
Date Of Driving Pass	22/09/1997
Driving experience	24 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93829639
Alt. Phone Number	+65-93829639
Email Address	CWCONS_LOKE@YAHOO.COM.SG
Address	1 JURONG LAKE LINK
Address complement	#09-01
Postcode	648160
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	TRACY ZHOU
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK2921D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 10/11/21


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 10/11/21

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 9/11/21 @ ABOUT 6:20PM, I WAS TRAVELLING ALONG
 PIE TOWARDS CHANGI ON EXTREME RIGHT LANE, IN MY
 VEHICLE SMW 9881P. AS I WAS APPROACHING NEAR
 FILTER EXIT TO UPPER SERANGOON / CTE, VEHICLES
 AHEAD SLOWED DOWN, HENCE I SLOWED DOWN AS
 WELL. SUDDENLY I FELT AN IMPACT & REALIZED
 VEHICLE SLK 2921D COLLIDED ONTO MY VEHICLE'S
 REAR PORTION. NO INJURIES. I HAVE ONE
 PASSENGER.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 10/11/21
  10/11/21
 Policyholder's Signature Driver's Signature
 Date & Time: (If driver is not the policyholder)

Reporting Centre Personnel's Signature
 Name:













GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 4 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6324 0030 Fax (65) 6324 0030
 Operating Hours: Monday to Friday, 09:00 – 17:00
 UEN: S66299300 / GI Reg. No: SA00017795

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : SC1S21BA0003 Vehicle Registration No: SMW 9881P
 Name (as shown in NRIC) : LOKE WEE CHOONG NRIC/FIN/Passport No : S XXXX300C
 (*Vehicle Driver / Vehicle Owner) (* Please delete as appropriate)
 Address : 1 JURONG LAKE LINK #08-01 Singapore (648160)
 Contact (Tel) : _____ Mobile No. : 9382 9639
 Email Address : CWCONS_LOKE@YAHOO.COM.SG
 Date of Accident : 09.11.2021 Time of Accident : 1820 HR
 Place of Accident : PIE TOWARDS CHANGI
 Insurance Company: AIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I WISH TO AMEND MY EMAIL ADDRESS TO CWCONS_LOKE@YAHOO.COM.SG


 Policyholder / Driver's Signature
 Date: 8 DEC 2021

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 Date:

AIG		CERTIFICATE OF INSURANCE	
TOYOTA AUTO PROTECTOR PRIVATE VEHICLE			
Name of Policyholder	: LOKE WEE CHOONG	Vehicle No.	: SMW9881P
Period of Insurance	: 11 Dec 2020 To 10 Dec 2021	Policy No.	: 2070171431
Engine No.	: 1ZR0G35650	Endorsement No.	:
Chassis No.	: MR2BE3BEX00011911	Issued Date	: 11 Dec 2020
ABOUT THE COVER			
Make/Model	: TOYOTA COROLLA ALTIS 1.6	Sum Insured	: Market Value
Engine Capacity/Tonnage	: 1,598.00 CC	Off Peak Car	: No
Driver Restriction	: NA	First Year of Registration	: 2020
Person or Classes of Persons Entitled to Drive*		Insuring with COE/PARF	: Yes
a) The Policyholder b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition. You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.			
Age Condition	: All Age Condition	Mileage Condition	: Unlimited Mileage
Limitation as to use*	Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.		
Loss of Use 1500cc - 1600cc	* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.		
EXCESS			
Section 1	Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600		
Section 2	Property Damage - \$0		
Windscreen	: \$100		
Named Driver and Excess (where applicable)	LOKE WEE CHOONG - \$600 (Own Damage), \$600 (Flood Cover)		
APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)			
1. Toyota Bodycare Centre (For accident repair & accident reporting) Add: 2 Pandan Crescent Singapore 128462 Tel: 6631 1188 2. Toyota Bodycare Centre (For accident repair & accident reporting) Add: 17 Ubi Road 4 Singapore 408611 Tel: 6631 1688 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.			
IMPORTANT NOTES			
Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD			
(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).			
0504667212	AIG Asia Pacific Insurance Pte. Ltd.		
INCHCAPE AUTO TOYOTA - BSTL025	This computer generated document does not require a signature.		
33 LENG KEE ROAD	Daloon Aileen Zabala		
SINGAPORE 159102			
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.			
78 Shenton Way #09-16 AIG Building S079120 T: +65 6419 3000 www.aig.sg		AIG Asia Pacific Insurance Pte. Ltd.	



RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Date of Request: 28/12/2021

Your Ref No: **SB/PO/Acc/2021-9693**

Dear Sir/Madam,

Date of Accident: 09/11/2021 00:00 (SGT)

Vehicle No: SMW9881P

Place of Accident: PIE, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLK2921D	PIE, Singapore	(29.00)	1	(27.10)
GST Amount				(1.90)
Total Amount Due (GST Inclusive)				(29.00)

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/11/2021 17:19 (SGT)
Date of Accident 09/11/2021 18:10 (SGT)
Exact Location of Accident PIE, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK2921D

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner GRAB RENTALS PTE LTD

VEHICLE PARTICULARS

Manufacturer Mazda
Model 3
Variant -
Vehicle Category Private hire
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number D21MFL0000447
Cover Note Number -

DRIVER

Name of Driver LAW BOON CHYE (LUO WENCAI)
NRIC No S7416730F
Address BLK 64 KALLANG BAHRU #02-391
Address complement -
Postcode 330064
Does Driver Own Other Vehicles? No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
Weather Conditions Raining

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Was anybody injured in the Accident? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1

CIRCUMSTANCES OF ACCIDENT

ON THE 09/11/2021 AT ABOUT 1810 HOURS, I WAS DRIVING VEHICLE A (SLK2921D) ON LANE 1 ALONG PIE (CHANGI) WHEN THERE IS PILE UP TRAFFIC AHEAD AND VEHICLE B (SMW9881P) EXECUTED AN EMERGENCY BRAKE INFRONT OF ME AND I WAS UNABLE TO BRAKE IN TIME AND REAR ENDED VEHICLE B. NOBODY WAS INJURED.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMW9881P
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver -
Insurance Company Name -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

[Handwritten Signature]
10/11/21 1440
[Handwritten Signature]

Sketch Plan



Describe Circumstances of the Accident

ON THE 09/11/2021 AT ABOUT 1810 HOURS, I WAS DRIVING VEHICLE A (SLK2921D) ON LANE 1 ALONG PIE (CHANGI) WHEN THERE IS PILE UP TRAFFIC AHEAD AND VEHICLE B (SMW9881P) EXECUTED AN EMERGENCY BRAKE INFRONT OF ME AND I WAS UNABLE TO BRAKE IN TIME AND REAR ENDED VEHICLE B. NOBODY WAS INJURED.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



10/11/21 1840





















Enquire Vehicle Owner Details (As At 09 Nov 2021 / 18:20:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

201617200G

Owner Name:

GRAB RENTALS PTE. LTD.

Registered Address Type:

**Private Residential (Condo Apt or House) /
Shopping / Office Complexes**

Registered Block/House No.:

6

Registered Street Name:

SHENTON WAY

Registered Unit No.:

38 - 01

Registered Building Name:

-

Registered Postal Code:

068809

Vehicle Insurance Details

Vehicle No.:

SLK2921D

Make Description/Model:

**MAZDA / MAZDA3 4-DOOR SEDAN 1.5L SP.
6EAT**

Insurance Company Name:

MSIG INSURANCE (SINGAPORE) PTE LTD

Insurance Company Name:

INDIA INT'L INS PTE LTD



Thank you

Ong Hwee Ling Pauline has successfully logged out.
Your last login date and time was 10 Nov 2021, 12:07:01.
To return to ONE.MOTORING, please click [here](#)
For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)
1	Vehicle	SLK2921D		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

TOH PAINTING & SERVICES PTE LTD
Block 3 Woodlands Road Unit 391C&G
Yew Tee Industrial Estate
Singapore (677966)

Phone 67631055
Fax 67636151
GST Number 20-0311427-D

TAX INVOICE

LOKE WEE CHOONG
1 JURONG LAKE LINK
#09-01
SINGAPORE 648160

Phone: 9382 9639

Fax: -

Invoice Number: 102719

Date	Delivery	Customer	Order Number	Packing Slip	Internal Reference	Sales Person	Page
22-Dec-21		SMW9881P	T / ALTIS		SMW9881P		1

Code	Description	Quantity	Unit Price	Discount	Amount
------	-------------	----------	------------	----------	--------

COST OF REPAIRS

TO SUPPLY SPARE PARTS, REPAIR / PANEL BEATING, WELDING, WIRING CHECKING, PUTTY AND SPRAY PAINTING & OTHER CHARGES	1	\$7,450.00		\$7,450.00
--	---	------------	--	------------

CONTRACT REPAIR AS RECOMMENDED.

SGD: SEVEN THOUSAND NINE HUNDRED SEVENTY-ONE & CENTS FIFTY ONLY.



Authorized Signature for TOH PAINTING & SERVICES PTE LTD

Total Net	\$7,450.00
GST	\$521.50
Invoice Total Including GST	\$7,971.50

TLC CAR RENTAL

Block 3 Woodlands Road 391C Yew Tee Industrial Estate Singapore 677966

Tel: 6760 7542 Fax: 6763 6151

VEHICLE RENTAL AGREEMENT

No. 31463

VEHICLE NO.	SXC3A71G	MAKE / MODEL	T / CAMRY
-------------	----------	--------------	-----------

RENTAL DETAILS

DATE OUT / TIME	10/11/21 @ 11:10 AM
DATE IN / TIME	17/11/21 @ 12:50 PM
NO. OF DAYS	7
PER DAY CHARGES	\$100/-
TOTAL	\$700/-
EXCESS DOLLARS	\$1,500/-

HIRER'S / DRIVER'S DETAILS

HIRER / NRIC NO.	LOKE WEE CHOONG / S7378300C
ADDRESS OF HIRER	1 JURONG LAKE LINK #09-01 S648160
CONTACT NO.	93829639
DRIVER / NRIC NO.	} AS ABOVE
ADDRESS OF DRIVER	
CONTACT NO.	

ATTENDED BY: XIUHUI

TERMS & CONDITIONS

HIRER / DRIVER SHALL BEAR ALL PARKING & TRAFFIC-RELATED SUMMONS.
HIRER / DRIVER SHALL ENSURE VEHICLE USAGE WITHIN SINGAPORE ONLY, UNLESS PERMITTED BY VEHICLE OWNER.
HIRER SHALL NOT USE VEHICLE FOR ANY UNAUTHORIZED USAGES.

DECLARATION

ABOVE-MENTIONED HIRER / DRIVER HEREBY DECLARE NO MOTOR ACCIDENTS OCCURENCES DURING HIRED PERIOD STATED ABOVE.			
10/11/21		17/11/21	
DATE OUT	HIRER'S SIGNATURE	DATE IN	HIRER'S SIGNATURE

TLC CAR RENTAL

Block 3 Woodlands Road 391C Yew Tee Industrial Estate Singapore 677966
Tel: 6760 7542 & 6763 1055 Fax: 6763 6151

TO: Loke Wee Choong
1 Jurong Lake Link
#09-01
Singapore 648160

Date 10.11.2021
Agreement No. 31463 / 9881
Invoice No. 100423

DESCRIPTION

AMOUNT

To supply one unit of air-conditioned T / Camry
Vehicle Reg No. SKC 3971G rental as from
10.11.2021 1110 hours to 17.11.2021 1250 hours.


\$700.00

7 days x \$100.00 per day

SGD: Seven hundred only

\$700.00

TLC Car Rental



Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

INVOICE

To: Loke Wee Choong
1 Jurong Lake Link
#09-01
Singapore 648160

Date : 15/12/2021
Invoice No : IV21-12014/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SMW 9881P (Inclusive Of Photographs And Transport Charges) Our reference : CAS/21-12/014	\$519.00
Total	\$519.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
Blk 2 Rivervale Link, #09-02 Singapore 545040
Tel/Fax: 6886 1106 Mobile: 9007 5234
Email: constant_as@yahoo.com.sg
RCB No. 53138015K

Automobile Inspection Report

To: Loke Wee Choong 1 Jurong Lake Link #09-01 Singapore 648160	Date : 15/12/2021 Reference No : CAS/21-12/014		
<u>General Information</u>			
Registration No. : SMW 9881P Accident Date : 09/11/2021			
<u>Particulars of Damaged Vehicle</u>			
Colour : Grey Engine Capacity : 1598 cc Mileage (KM) : 26286 Chassis No. : MR2BE3BEX00011911 Registration Date : 11/12/2020	Make & Model : Toyota Corolla Altis Pre-Accident Condition : Good Engine No. : 1ZR0G35650 Steering : In Order Brake : In Order		
<u>Tyre Condition</u>			
R/H Front Tyre	Size	Make	Balance
L/H Front Tyre	205/55R16	MICHELIN	80%
R/H Rear Tyre	205/55R16	MICHELIN	80%
L/H Rear Tyre	205/55R16	MICHELIN	80%
<u>Inspection</u>			
Repairer : Toh Painting & Services Pte Ltd Blk 3C Woodlands Road, 391C/G Yew Tee Industrial Estate, Singapore 677966			
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate	: \$9,943.26		
Revised Amount	: \$7,450.00		
Less Excess	: -		
Nett Total	: \$7,450.00		
<u>Remarks</u>			
(A) Survey was done on 11/11/2021			
(B) The survey was conducted entirely on WITHOUT PREJUDICE basis.			
(C) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : SMW 9881P

Our ref : CAS/21-12/014

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Bootlid	Dented/Buckled	942.65	942.65
2	1pc	Bootlid lock	Bent/Jammed	439.56	439.56
3	1pc	Bootlid lock catch	Bent	61.59	61.59
4	1pc	Bootlid weatherstrip	Distorted	230.56	230.56
5	2pcs	Bootlid hinge @ \$90.09	Bent/Twisted	180.18	180.18
6	2pcs	Bootlid rubber stopper @ \$20.79	Necessary	41.58	41.58
7	1pc	Bootlid emblem logo	Necessary	61.16	61.16
8	1pc	Bootlid emblem Corolla	Necessary	44.99	44.99
9	1pc	Bootlid emblem Altis	Necessary	50.22	50.22
10	2pcs	Bootlid reverse lamp @ \$1,343.87	Cracked/Broken	2,687.74	2,687.74
11	1pc	Bootlid garnish	Serviceable	219.95	-
12	2pcs	Taillamp @ \$813.78	Cracked/Broken	1,627.56	1,627.56
13	2pcs	Taillamp lower bracket @ \$72.55	Broken	145.10	145.10
14	1pc	Rear bumper	Dented/Deformed	650.76	650.76
15	2pcs	Rear bumper reflector @ \$54.56	Serviceable	109.12	-
16	1pc	Rear bumper reinforcement	Dented/Bent	372.85	372.85
17	2pcs	Rear bumper retainer @ \$110.72	Broken	221.44	221.44
18	1pc	Rear bumper tow hook cover	Serviceable	20.79	-
19	1pc	Rear end panel	Dented/Warped	736.45	736.45
20	1pc	Rear end panel garnish	Deformed	307.56	307.56
21	1pc	Rear end panel garnish cover	Deformed	67.66	67.66
22	2pcs	Reverse sensor @ \$265.10	Damaged	530.20	530.20
				9,749.67	9,399.81
Less 25%				(2,437.41)	(2,349.95)
Sub total				7,312.26	7,049.86
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Bootlid inner trim board clip	Necessary	34.00	34.00
2	1set	Rear end panel garnish clip	Necessary	22.00	22.00
3	1set	Rear bumper clip	Necessary	55.00	55.00
Part total				7,423.26	7,160.86

Constant Appraiser Services

Vehicle No : SMW 9881P

Our ref : CAS/21-12/014

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES</u>			
1		Repair & replace damaged parts		1,000.00	900.00
2		Spray paint affected area		1,200.00	1,000.00
3		Remove & refix trim board & garnish		100.00	80.00
4		Remove & refix reverse sensor		80.00	60.00
5		Check rear wiring system		40.00	20.00
6		Spray anti rust on affected area		100.00	60.00
			Grand total	9,943.26	9,280.86
Recommended cost of lump sum repair (To its pre-accident condition)					7,450.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$7,450.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,


Constant Appraiser Services

Lim Yong Tian (Sebastian)
 Licensed Appraiser
 Adv. Dip. In Mechanical Engineering (AUS)
 MSAAA

Constant Appraiser Services




Constant Appraiser Services



Constant Appraiser Services






Constant Appraiser Services




Constant Appraiser Services




Constant Appraiser Services



Constant Appraiser Services





Constant Appraiser Services

















Constant Appraiser Services



Constant Appraiser Services



