Rvf3-1

(08/11/13) wef

ASS. REC. BY: Farm

REF: CS3/GRB21011481/Rvf3

300 c

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMW 9881P

at Workshop m/s TOH PAINTING & SVC P/L

of BLK C3, WOODLANDS RD 391-C YGNTEE

Insured: III SLK 2921D

Policy No. D21MFL0000447

Claims No. MFL2021D0004889

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 93K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMW 9881P Yr Regn: 2020 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA COROLLA ALTIS STA c.c 1598

Colour BLUE A/C: Insured / Std / NI / NA

Sp.Reading 26286 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR2BE3BEX0011911

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	09/11/21	D.O.I.	11/11/21

Survey held at TOH PAINTING

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 41K
	ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (3K-4K) / 5 days
15/11/21	Submit PRS
7/2/22	Submit LS $3800 (red 3650,48%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 7/2/22-typist

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) __S + RS, __SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

TOTAL

Report Format : TP

Lump Sum / I.B.I: ($)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	300C
Vehicle No.:	SMW9881P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS STANDARD (AUTO)(2WD)
Primary Colour:	Grey
Manufacturing Year:	2020
Engine No.:	1ZR0G35650
Chassis No.:	MR2BE3BEX00011911
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	$19,850.00
Original Registration Date:	11 Dec 2020
First Registration Date:	11 Dec 2020
Transfer Count:	0
Actual ARF Paid:	$19,850.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2030
PARF Rebate Amount:	$14,887.00
COE Expiry Date:	10 Dec 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	$40,714.00
COE Rebate Amount:	$36,966.00
Total Rebate Amount:	$51,853.00

The information contained herein is correct as at 11 Nov 2021

OK

Toyota Corolla Altis 1.6A Standard

Overview | Financial | Accessories | Similar | Research | Photos | Map

Price	$89,800		
Depreciation	$9,220 /yr View models with similar depre	**Reg Date**	14-Jul-2020 (8yrs 8mths 2days COE left)
Mileage	20,000 km (15.1k /yr)	**Manufactured**	2020
Road Tax	$742 /yr	**Transmission**	Auto
Dereg Value	$43,834 as of today (change)	**OMV**	$19,678
COE	$33,520	**ARF**	$19,678
Engine Cap	1,598 cc	**Power**	96.0 kW (128 bhp)
Curb Weight	1,315 kg	**No. of Owners**	1
Type of Vehicle	Mid-Sized Sedan		

Features

View specs of the Toyota Corolla Altis (2020)