

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

CS3/ASM22000187/Vty3e2

Page No.:1 of 1

	_						
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM22000187/Vty3e2			
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Date:	09/02/2022			
	ATTN: HO WINNIE		Code	: ASM			
1.		AIM)					
	Insured Veh.	SH 7729T	Veh. Inspected	SMQ 6321R			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	S2M03Q9J	Excess (\$)	0.00			
	Assign From	HO WINNIE	Assign Date	06/01/2022			
2. Vehicle Particulars & Condition							
	Make & Model	TOYOTA WISH	c.c	1798			
	Engine No.	HIDDEN	Year of Reg.	2016			
	Chassis No.	JTDGG20W50J005456	Colour	BLACK			
	Odometer	205549 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM			
	General	GOOD					
3.		Conditions of Tyres					
		Size	Make	Balance			
	R/H Front Tyre	225/45Z R17	NEXEN	6 mm			
	L/H Front Tyre	225/45Z R17	NEXEN	6 mm			
	R/H Rear Tyre	225/45Z R17	NEXEN	6 mm			
	L/H Rear Tyre	225/45Z R17	NEXEN	6 mm			
4. Description of Damages							
	THE VEHICLE SU						
5.		Ge	eneral Information				
	Accident Date	05/01/2022	Inspect Date / Time	06/01/2022 ( 03:00 PM )			

5.	General Information						
	Accident Date	05/01/2022	Inspect Date / Time	06/01/2022 ( 03:00 PM )			
	Survey held at	SPEEDWERKZ PTE LTD					
		13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807					

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. **Estimate Days of Repair** ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/ASM22000187/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**