



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHU XICHI EUGENE			Ref: CS/ASM22000216/Tty3e2 Date: 14/06/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMX 1565A	Veh. Inspected	SMS 42A
	Policy No.	VFX/P2440417	Coverage (\$)	0.00
	Claim No.	S2M03Q0R	Excess (\$)	0.00
	Assign From	CHU XICHI EUGENE	Assign Date	07/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLKSWAGEN GOLF GTI	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	WVWZZZ1KZ7U040342	Colour	GREY
	Odometer	223648 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	GOODYEAR	6 mm
	L/H Front Tyre	225/40 R18	GOODYEAR	6 mm
	R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
	L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/01/2022	Inspection Date	10/01/2022
	Survey held at	01-44 SYNERGY BUILDING		
	Repairer	TSL AUTO GARAGE		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	