

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1988 GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22000218/Kqf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Г	Date:	20/06/2022	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFQ 2868P	Veh. Inspected		SE 45U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10013268/EE	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		07/01/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES A200 (A)	c.c		1333	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	WDD1770872N010925	Colour		METALLIC GREY	
	Odometer	83379 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45 R18	MICHELIN		8 mm	
	L/H Front Tyre	225/45 R18	MICHELIN		8 mm	
	R/H Rear Tyre	225/45 R18	MICHELIN		8 mm	
	L/H Rear Tyre	225/45 R18	MICHELIN		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/01/2022	Inspection Date		17/01/2022	
	Survey held at	LIM TAN MOTOR PTE LTD				
		BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: