



MAP OF ROUTE TAKEN

Incident happen at Sembawang Airbase HQ carpark lot.




Route: Sembawang Airbase HQ carpark lot
Total Distance: 0 KM

VIEW OF INCIDENT SITE




Distance Travelled From SP: 0 KM
Remaining Distance to EP: 0 KM

PICTORIAL VIEW OF INCIDENT SITE



SCHEMATIC DIAGRAM OF INCIDENT



CLOSE-UP VIEW OF THE ACCIDENT VEHICLE(S)



Front View of MID 46334



Rear View of MID 46334



Right Side View of MID 46334



Left Side View of MID 46334



Zoomed In View of MID 46334

RESTRICTED

ANNEX G

STATEMENT OF DRIVER/WITNESS (SAF 1201)


SINGAPORE ARMED FORCES STATEMENT OF DRIVER/WITNESS

STATEMENT OF	PTE Dominic Ong Chin Kiat				ALIASES				
NRIC NO	T. 10921	AGE	19		MALE/FEMALE	Male			
EMPLOYMENT	SAF	DRIVING LICENCE NO			NATIONALITY	Singaporean			
DIALECT	Hokkien	LANGUAGE SPOKEN	English		TEL NO	[REDACTED]			
ADDRESS	[REDACTED]								
INTERPRETED BY		RANK		TIME		DATE		SIGN	
RECORDED BY		RANK		TIME		DATE		SIGN	
<p>On 28th December 2021, I reported to BDO room at 0640 hrs before proceeding to carry out the BOS of the minibus. After completing the BOS and the paper work which was signed by the BDO, I went to start the minibus for my morning ferry service duty. The vehicle I drove was the minibus (46334). After starting the car and performing reversing drill, I started to reverse. I focused too much on the rear view mirror so that I would not hit anything at the back but paid less attention to what was beside, particularly on my right. When I was turning out, I heard a scratching sound and I proceeded to stop the vehicle after hearing it. I stepped out of the car to examine the car that I grazed and found out that it had a few scratches and a small dent. I also found scratch marks on my minibus. The BDO ^{on duty} was also there to witness the accident.</p>									
DATE	28/12/2021		SIGNATURE OF DRIVER/ WITNESS		[Signature]				

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and interpreter.
Statement of witness must be signed by the witness.

**SINGAPORE ARMED FORCES
STATEMENT OF DRIVER/WITNESS**

STATEMENT OF		MEETAN CHOR MENG SLE 10912		ALIASES		-	
NRIC NO		[REDACTED]		AGE		42	
EMPLOYMENT		DRIVING LICENCE NO		[REDACTED]		MALE/FEMALE	
DIALECT		LANGUAGE SPOKEN		ENGLISH		NATIONALITY	
ADDRESS		[REDACTED]		TEL NO		[REDACTED]	
INTERPRETED BY		RANK		TIME		DATE	
RECORDED BY		RANK		TIME		DATE	
<p>I was locking GP car in Base Headquarter. A loud scratch sound was heard.</p> <p>I immediately turn my attention to the location and saw the Minibus (M10 46334) grazed my vehicle. Time of incident was around 0650 hr.</p> <p>T.O proceed to check his vehicle and found scratches on his forward right.</p> <p>My vehicle (SLE10912) had dents and scratches on left off on car body.</p> <p>I had witness after the initial scratch sound was heard. The vehicle was still in motion before the Minibus comes to a complete stop. The T.O was steering left and of the parking lot reversing.</p>							
DATE		28DEC2021		SIGNATURE OF DRIVER/ WITNESS			

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and interpreter.
Statement of witness must be signed by the witness.

TRAFFIC ACCIDENT REPORT (SAF 1202)

OFFICIAL(CLOSED)

**SINGAPORE ARMED FORCES
TRAFFIC ACCIDENT REPORT**

Instructions to driver:

- (1) This form is to be completed for all traffic accidents (both internal & external) involving MINDEF vehicles.
- (2) Arrange for the relevant columns to be carefully and fully completed as possible at the scene of the accident.
- (3) Refrain from doing or saying anything which could be interpreted as an admission of liability.
- (4) Report the accident in person (where applicable) to the nearest Police Station within 24 hours of its occurrence.
- (5) Submit the completed report together with the accompanying signed and witnessed prepared by yourself and service witnesses (if any) to the OC of your unit for transmission to the appropriate authorities.

GENERAL PARTICULARS OF THE ACCIDENT AND THE OTHER PARTY				
Date of Accident 28/12/2021	Time (hours) 0645	Place Sembawang air base		Type of Vehicle/Object Involved Minibus and civilian car
Make Mitsubishi	*L.H / R.H Drive NIL	Registration Number SLB 109/L	Year of Make NIL	
Name of Insurance Company Aviva @ comfort design spang	Driver's Name & Address [REDACTED]		Owner's Name & Address [REDACTED] # of -13	
Nature of damage (in fullest detail) – use continuation sheet if necessary Bump resulted in scratches and a dent on left rear. On right, small scratch on front right.			Report to NIL	
PARTICULARS OF WITNESSES				
Witnesses (if in SAF, state NRIC & Unit)	Name	Address		Tel No.
	TAN CHOR MONG	[REDACTED]		[REDACTED]
	S. 1725A 2022			
PARTICULARS OF INJURED PERSONS				
Witnesses (if in SAF, state NRIC & Unit)	Name	Address		Tel No.

Upon completion of the above columns, please make a sketch of the accident on the third page of this form

The Accident Slip below has been detached and given to _____ of _____

(This person should normally be driver of the other vehicle.

However, in exceptional circumstances, it may be given to a police officer if one appears on the scene.)

*Delete where applicable

If you have any enquiry, please contact us at Tel: [REDACTED]

[REDACTED]

PARTICULARS OF VEHICLE & DRIVER FOR WHICH THIS REPORT IS MADE

OFFICIAL(CLOSED)

OFFICIAL(CLOSED)

Make & nomenclature of service vehicle NISSAN		*L.H / R.H Drive Register No. M10		Date of last over-haul or inspection Next AVI: 27/10/22 Next AVI: 04/10/21		Present location of vehicle Sembawang Air Base MT workshop	
Describe (in fullest detail) the damage to service vehicle & load							
Name of Driver Dominic Ong Chin Kiat		NRIC T 0921		Rank PTE		Age 19	
Sex M		Date of Enlistment 17/05/2021		ORD 16/05/2023		Service Status <input type="checkbox"/> Regular <input checked="" type="checkbox"/> NSF <input type="checkbox"/> NSMen <input type="checkbox"/> NUSAF <input type="checkbox"/> Civilian	
Vocation <input type="checkbox"/> MT Specialist <input type="checkbox"/> Driver Class I <input type="checkbox"/> Driver Class II <input type="checkbox"/> Dual - Vocationalist <input type="checkbox"/> Non - Driver		SAF Driving Permit No. [REDACTED]		Class of Licence 3/4		Type of Licence <input checked="" type="checkbox"/> Permit Holder, trained by STTS <input type="checkbox"/> Permit Holder, not trained by STTS <input type="checkbox"/> Letter of Authority	
Date of issue 08/10/2021		Date Passed		Driving Experience		Category	
Service Licence 08/10/2021		Driving Test		Service Driving 0 yr 3 mth		A <input type="checkbox"/>	
Civilian Licence -		Service Licence 08/10/2021		Civilian Licence 0 - yr 0 - mth		B <input type="checkbox"/>	
Letter of Authority 08/10/2021		Civilian Licence -		Mileage Driven by Driver 1163 km		C <input checked="" type="checkbox"/>	
D <input type="checkbox"/>		Number of previous accidents in which you have been: 0		Number of attempts before passing driving test 2			
Involved <input type="radio"/> To Blame.....							

*Delete where applicable

Name Dominic Ong Chin Kiat	Rank PTE	Service No. 92373471	Vehicle No. M10 46334
Unit 706 SQN	Place of Accident Sembawang Air Base HQ	Date and Time 28/12/21 0650	

OFFICIAL(CLOSED)

OFFICIAL(CLOSED)

SINGAPORE AMED FORCES

GENERAL INFORMATION OF THE ACCIDENT																																									
Driver's Degree of injury <input type="checkbox"/> Fatal <input type="checkbox"/> Serious <input type="checkbox"/> Minor <input checked="" type="checkbox"/> No injury		Other Party's Degree of Injury <input type="checkbox"/> Fatal <input type="checkbox"/> Serious <input type="checkbox"/> Minor <input checked="" type="checkbox"/> No injury		Weather <input type="checkbox"/> Rainy <input type="checkbox"/> Drizzling <input checked="" type="checkbox"/> Fine																																					
		Visibility <input checked="" type="checkbox"/> Clear <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Others (Specify)		Classification of Accident <input type="checkbox"/> External <input type="checkbox"/> Fatal <input type="checkbox"/> Major <input checked="" type="checkbox"/> Minor <input checked="" type="checkbox"/> Internal																																					
Location: Accident occurred on (state road) <u>one way road</u> at <u>1</u> km (specify land marks, if any) <u>Sambarway Cir Side HQ car park</u> If accident occurred at a junction, name the road forming the junction. <u>Sambarway Cir Side HQ car park</u> <u>NIL</u>			Area of Accident <input checked="" type="checkbox"/> Camp Area <input checked="" type="checkbox"/> Car Park <input type="checkbox"/> Training Area <input type="checkbox"/> Overseas <input type="checkbox"/> Near school Vicinity <input type="checkbox"/> Public Housing Estate <input type="checkbox"/> Private Residential Area <input type="checkbox"/> Factory <input type="checkbox"/> Shopping Complexes <input type="checkbox"/> Shop Houses <input type="checkbox"/> In CBD Area (During non operational hours) <input type="checkbox"/> In CBD Area (During operational hours) <input type="checkbox"/> Others (specify)																																						
Type of Road <input type="checkbox"/> Main Road <input checked="" type="checkbox"/> One-way <input type="checkbox"/> Two-way <input type="checkbox"/> Dual-Carriage way <input type="checkbox"/> Multi-Carriage way <input type="checkbox"/> Side Road <input type="checkbox"/> Minor to Major <input type="checkbox"/> Major to Minor <input type="checkbox"/> Others (Specify)		Road Surface <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Wet <input type="checkbox"/> Oily <input type="checkbox"/> Sandy <input type="checkbox"/> Others (Specify)		Road Feature <input type="checkbox"/> Narrow <input type="checkbox"/> Bend <input type="checkbox"/> Merging <input type="checkbox"/> U-turn <input checked="" type="checkbox"/> Straight Road <input type="checkbox"/> Sharp Turn <input type="checkbox"/> Blind Corner <input type="checkbox"/> Bridge <input type="checkbox"/> T-junction <input type="checkbox"/> Y-junction <input type="checkbox"/> X-junction <input type="checkbox"/> Box-junction <input type="checkbox"/> Flyover <input type="checkbox"/> Private Road <input type="checkbox"/> Others (Specify)																																					
				Road Speed Limit <input checked="" type="checkbox"/> < 40km/h <input type="checkbox"/> 50km/h <input type="checkbox"/> 60km/h <input type="checkbox"/> 70km/h <input type="checkbox"/> 80km/h Traffic Volume <input type="checkbox"/> Heavy <input type="checkbox"/> Medium <input checked="" type="checkbox"/> Light																																					
Type of Collision (i) Between moving Vehicle <input type="checkbox"/> Head On <input checked="" type="checkbox"/> Head to rear <input type="checkbox"/> Head to side <input type="checkbox"/> Hit & Run <input type="checkbox"/> Side Swipe (Same Direction) <input type="checkbox"/> Side Swipe (Different direction) <input type="checkbox"/> Others (Specify) (ii) Moving vehicle against <input checked="" type="checkbox"/> Parked vehicle <input type="checkbox"/> Lamp post <input type="checkbox"/> Animals <input type="checkbox"/> Road divi <input type="checkbox"/> Pedestrian <input type="checkbox"/> Others (Specify)			Manoeuvre of Vehicle before Accident <input type="checkbox"/> Stationary <input type="checkbox"/> Overtaking <input checked="" type="checkbox"/> Reversing <input type="checkbox"/> Stopping / Slowing Down <input type="checkbox"/> Moving Off <input type="checkbox"/> Changing Lane <input type="checkbox"/> Negotiating U-turn <input type="checkbox"/> Entering / Leaving Shoulder <input type="checkbox"/> Turning left - Waiting <input type="checkbox"/> Turning right - Waiting <input type="checkbox"/> Driving Ahead <input type="checkbox"/> Others (Specify)																																						
Probable Cause of Accident <table border="0"> <thead> <tr> <th>Mil</th> <th>Civ</th> <th></th> <th>Mil</th> <th>Civ</th> <th></th> </tr> </thead> <tbody> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Failure to give way</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Improper Overtaking</td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Turning without care</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Tailgating</td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Changing Lanes</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Exceeding Speed Limit</td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Skidding</td> <td><input checked="" type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Others (Specify) <u>poor judgement on handling</u></td> </tr> <tr> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Inattentive Driving</td> <td><input type="checkbox"/></td> <td><input type="checkbox"/></td> <td>Illegal</td> </tr> </tbody> </table>						Mil	Civ		Mil	Civ		<input type="checkbox"/>	<input type="checkbox"/>	Failure to give way	<input type="checkbox"/>	<input type="checkbox"/>	Improper Overtaking	<input type="checkbox"/>	<input type="checkbox"/>	Turning without care	<input type="checkbox"/>	<input type="checkbox"/>	Tailgating	<input type="checkbox"/>	<input type="checkbox"/>	Changing Lanes	<input type="checkbox"/>	<input type="checkbox"/>	Exceeding Speed Limit	<input type="checkbox"/>	<input type="checkbox"/>	Skidding	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Others (Specify) <u>poor judgement on handling</u>	<input type="checkbox"/>	<input type="checkbox"/>	Inattentive Driving	<input type="checkbox"/>	<input type="checkbox"/>	Illegal
Mil	Civ		Mil	Civ																																					
<input type="checkbox"/>	<input type="checkbox"/>	Failure to give way	<input type="checkbox"/>	<input type="checkbox"/>	Improper Overtaking																																				
<input type="checkbox"/>	<input type="checkbox"/>	Turning without care	<input type="checkbox"/>	<input type="checkbox"/>	Tailgating																																				
<input type="checkbox"/>	<input type="checkbox"/>	Changing Lanes	<input type="checkbox"/>	<input type="checkbox"/>	Exceeding Speed Limit																																				
<input type="checkbox"/>	<input type="checkbox"/>	Skidding	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Others (Specify) <u>poor judgement on handling</u>																																				
<input type="checkbox"/>	<input type="checkbox"/>	Inattentive Driving	<input type="checkbox"/>	<input type="checkbox"/>	Illegal																																				

OFFICIAL(CLOSED)

POLICE REPORT

SINGAPORE

**POLICE REPORT (NP299)**

Police Station Of Origin

Date/Time Report Made 28/12/2021 17:22	Vide Report No.	Station Diary No.
Name Of Informant DOMINIC ONG CHIN KIAT	Address [REDACTED]	
ID Type / ID No. NRIC NO. [REDACTED]	Contact No. Home/Office: [REDACTED]	Mobile: [REDACTED]
Nationality SINGAPORE CITIZEN	Email Address DOMINIC.ONG5@GMAIL.COM	
Occupation National Service Full Time	Sex Male	Age 19
Institution/School Name	Date of Birth 12/01/2002	Race Chinese
Date/Time Of Incident 28/12/2021 06:40 - 28/12/2021 06:55	Location Of Incident [REDACTED]	

Brief details.

On 28th December 2021, I reported to the BDO room at 0640Hrs before proceeding to carry out the BOS of the minibus. After completing the BOS and the paperwork which was signed by the BDO on duty, I went to start the minibus for my morning ferry service duty. The vehicle I drove was the minibus MID 46334. After starting the car and performing reversing drill, I started to reverse. I focused too much on the rear view mirror so that I would not hit anything at the back but paid less attention to what was beside, particularly on my right. When I was turning out, I heard a scratching sound and I proceeded to stop the

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/12/2021 17:22
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

vehicle after hearing it. I stepped out of the car to examine the car that I grazed and found out that it had a few scratches and a small dent. I also found scratch marks on my minibus. The BDO on duty was also there to witness the accident

Subjects Involved			
Victim			
Person Name	TAN CHOR MENG		
ID Type	NRIC NO	ID No	
Gender	Male	Age	42
Race	Chinese	Language	English
Occupation	National Service Full Time	Address	
Mobile No			

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/12/2021 17:22
Officer In-Charge Of Case:	Classification Of Case:



SINGAPORE
POLICE FORCE



1 of 3

POLICE REPORT (NP299)

Police Station Of Origin
Woodlands Division HQ
1 Woodlands Street 12 SINGAPORE 738622
Tel No:1800-4660000

Date/Time Report Made 28/12/2021 18:42	Vide Report No.	Station Diary No.
Name Of Informant TAN CHOR MENG	Address	
ID Type / ID No. NRIC NO. [REDACTED]	Contact No. Home/Office: [REDACTED]	Mobile: [REDACTED]
Nationality SINGAPORE CITIZEN	Email Address johnnyjohnny821@hotmail.com	
Occupation Flight engineer	Sex Male	Age 42
Institution/School Name	Date of Birth 12/08/1979	Race Chinese
Date/Time Of Incident 28/12/2021 06:50 - 28/12/2021 06:55	Location Of Incident Sembawang Airbase, Base Headquarter.	

Brief details.

I was about 4 metres away when the accident happen. I was locking up another Military Vehicle when I heard a loud scratching sound. I immediately turn my attention to the location.

I saw a military minivan (MID 46334) reversed into my personal owned vehicle (SLE 1091L) which was parked. The military minivan was still in motion when my attention was turned to the location of the sound.

The military minivan driver disembarked to check his vehicle. The military van have some scratches on

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 28/12/2021, 18:42
Officer In-Charge Of Case:	Classification Of Case:



SINGAPORE
POLICE FORCE



2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

front right below the headlight.

My vehicle (SLE 1091L) had a dent and large scratch marks on the left rear of my car body.

Subjects Involved			
Suspect			
Person Name	Ong Chin Kiat		
ID Type	OTHERS / 11B	ID No	[REDACTED]
Gender	Male	Age	18-22
Race	Chinese	Language	English
Occupation	Other car and light goods vehicle drivers nec	Mobile No	[REDACTED]
Relation To Informant	Nil		
Victim			
Person Name	TAN CHOR MENG		
ID Type	NRIC NO	ID No	[REDACTED]
Gender	Male	Age	42
Race	Chinese	Language	English
Occupation	Flight engineer	Address	[REDACTED]
Mobile No	[REDACTED]	Is Informant A Victim?	Yes
Person Name	TAN CHOR MENG (Informant)		

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:
28/12/2021 18:42

Classification Of Case: