

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22000241/Eny3e2	
	8 SHENTON WAY AXA TOWERSING		Date:	30/11/2022	
	ATTN: NG STACE	Υ	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 4772G	Veh. Inspected	BICYCLE	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S2M03QEY	Excess (\$)	0.00	
	Assign From	NG STACEY	Assign Date	07/01/2022	
2. Vehicle Particulars & Condition					
	Make & Model	GIANT DEFY ADVANCED PRO 2	c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	42 TUBELESS	GIANT	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	42 TUBELESS	GIANT	5 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE BICYCLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	28/12/2021	Inspection Date	10/01/2022	
	Survey held at	TAY JUNCTION			
	733 BUKIT TIMAH ROAD, #01-01, SECOND AVENUE JUNCTION, SINGAPORE 269748				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			
	1				