

141

ASSIGNMENT

Veh No: SMS 39/R. Yr Regn: 2020 / March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit C.C. 1317

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 23/81 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 6K33423630 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: **F: 175/70R14**

R: 175/70 RN

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 03/01/22

Survey held at Advance

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

Nett:

☐ : Prel. Report

☐ : Final Report

Add Fee: : Site Insp (\$)

☐ Site Insp. (\$)

☐ Interview (\$

Resurvey No. of Trip:

☐ Interview (\$

Tech Invs (3)

Westland 18

Transportation:

3 + PSE. S

Choice

M. Cifuentes