

ASS. REC. BY:

REF:

CC4/LPC 22000324/Rpa3

262c

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNA 27655at Workshop m/s PERFORMANCEof 303, ALEXMORA RDInsured: LPC

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 229k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No:

SNA 27655Yr Regn: 2021 / JUNType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 520I ADAPLED L.C.C 1998

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

03319

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 72AG 040CG 04380Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/01/22

D.O.I.

21/02/22

Survey held at

PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 127K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (%)

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 60555  
Date Estimated : 10/01/2022  
Prepared By : Foong Shiuh Jye

Page No. : 1 of 5

## - ESTIMATE REPAIR FOR -

Xu Shuzheng  
56 Edgedale Plains  
#03-11

Singapore 828822

## - ACCOUNT - 158

Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNA2765S	WBA72AG040CG04380	15/06/2021	520i Sedan	12

## DESCRIPTION

To replace front bumper including to knock out dented area caused by the accident

850 ~~1,275.00~~

To respray front bumper

986 ~~1,038.00~~

To replace left headlight.

? 456 ~~481.00~~

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

168 ~~177.00~~

To check electrical wiring system at the front section for proper function including adjustment of headlights.

168 ~~177.00~~

Sundries.

? 150.00

Total Labour 1: 3,298.00

## DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
# LH RUBBER STRIP (BASIS) ?	1	38.25	38.25
LH GRILLE COVER MU /	1	83.60	83.60
# IMPACT ABSORBER TOP (ECE) ?	1	75.00	75.00
# FRT BUMPER PANEL PRIMED (PDC) soc /	1	1,405.95	1,405.95
# FRONT GRILLE (BASIS) ?	1	351.40	351.40
GRID CENTRE (BASIS) ?	1	97.50	97.50
# LH GRILLE AIR INLET OPEN (BA) ?	1	83.60	83.60
# AIR FLAPS TOP ?	1	287.25	287.25
# AIR FLAPS BOTTOM ?	1	273.55	273.55
AIR DUCT RADIATOR BOTTOM ?	1	78.10	78.10
LH HEADLIGHT LED AHL ?	1	4,654.85	4,654.85

Total Parts : 7,429.05



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 60555  
Date Estimated : 10/01/2022  
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNA2765S	WBA72AG040CG04380	15/06/2021	520i Sedan	12

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 21/02/22 @ 11:25 Excess S\$ \_\_\_\_\_

Surveyor's Name RASUL Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

Reg before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	3,298.00
Parts	:	7,429.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	750.89

Grand Total : 11,477.94

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 05/01/2022 15:51 (SGT)  
Date of Accident ..... 05/01/2022 11:00 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... 462 CRAWFORD LANE #01-61 S 190462  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SNA2765S

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... XU SHUZHENG  
NRIC No ..... SXXXX262C  
Email Address ..... TONYXUPH@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-90097658  
Alternative Phone No ..... (Home) +--

#### VEHICLE PARTICULARS

Manufacturer ..... BMW  
Model ..... 520i  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1998

#### INSURANCE COMPANY

Name of Insurance Company ..... Liberty Insurance Pte Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... -  
Cover Note Number ..... C0119110

#### DRIVER

Name of Driver ..... DU HONG MEI  
NRIC No ..... SXXXX511F



Date Of Birth	26/12/1972
Occupation	Indoor
Date Of Driving Pass	23/12/2014
Driving experience	7 YEARS AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-90673107
Alt. Phone Number	-
Email Address	MUYUMELANIE@GMAIL.COM
Address	56 EDGEDALE PLAINS
Address complement	#03-11 RIVER ISLES
Postcode	828822
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV2547E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

ed Cos

PJWS

spect V

orkshc

ba

ured:

olicy N

laims

Sum I

(Ci

Mak

F



**IMPORTANT NOTICE**

1. please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:






**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

My wife DU HONGMEI was driving SNA2765S at the said location around 11:02AM on Jan. 5, 2022 to look for a parking lot. When she spotted there were no available car lot, and saw the car SKV2547E was reversing, so she stopped the car and wait, there were enough space for the reversing car to pass. The car SKV2547E hit the car SNA2765S during reversing, and scratched the front.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	262C
Vehicle No.:	SNA2765S
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2022
Vehicle Make:	B.M.W.
Vehicle Model:	520i ADAP LED HL
Primary Colour:	Black
Manufacturing Year:	2020
Engine No.:	12046248B48B20A
Chassis No.:	WBA72AG040CG04380
Maximum Power Output:	137.2 kW (183 bhp)
Open Market Value:	\$49,333.00
Original Registration Date:	15 Jun 2021
First Registration Date:	15 Jun 2021
Transfer Count:	0
Actual ARF Paid:	\$61,067.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2031
PARF Rebate Amount:	\$45,800.00
COE Expiry Date:	14 Jun 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,109.00
COE Rebate Amount:	\$55,980.00
Total Rebate Amount:	\$101,780.00

The information contained herein is correct as at 22 Feb 2022

OK



# BMW 5 Series 520i Mild Hybrid Luxury

Overview

Financial

Accessories

Similar

Research

Photos

Map

**SUPREME**

DO WHAT YOU LOVE

Price **\$230,988**

Depreciation **\$21,270 /yr**  
View models with similar depre

Reg Date **26-Jul-2021**  
(9yrs 5mths 3days COE left)

Mileage **4,500 km**

Manufactured **2020**

Road Tax **\$1,210 /yr**

Transmission **Auto**

Dereg Value **\$92,791 as of today (change)**

Fuel Type **Petrol-Electric**

COE **\$61,112**

OMV **\$49,333**

Engine Cap **1,998 cc**

ARF **\$61,067**

Curb Weight **1,610 kg**

Power **137.2 kW (183 bhp)**