

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	873W
Vehicle Details	
Vehicle No.:	XB8691H
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jan 2022
Vehicle Make:	SCANIA
Vehicle Model:	P360CB6X4MHZ
Primary Colour:	Multicolor
Manufacturing Year:	2016
Engine No.:	6948461
Chassis No.:	YS2P6X40005429122
Maximum Power Output:	-
Open Market Value:	\$112,852.00
Original Registration Date:	05 Dec 2016
First Registration Date:	05 Dec 2016
Transfer Count:	2
Actual ARF Paid:	\$5,643.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Dec 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,002.00
COE Rebate Amount:	\$23,981.00
Total Rebate Amount:	\$23,981.00

The information contained herein is correct as at 12 Jan 2022

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/01/2022 12:12 (SGT)
Date of Accident	04/01/2022 00:10 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	AYE (AFTER SOUTH BUONA VISTA ROAD EXIT 8)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XB8691H
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TEE ENVIRONMENTAL PTE LTD
Company Reg No	2XXXXX873W
Email Address	laykeng.low@teeinfra.com
Mobile Phone No	(Phone) +65-91219367
Alternative Phone No	(Office) +65-63831703

VEHICLE PARTICULARS

Manufacturer	Scania
Model	P360CB 6X4MHZ
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	12742

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine Insurance Singapore Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	21-MJ001332-R03
Cover Note Number	-

DRIVER

Name of Driver	ABU KHUROIAH BIN ALI
Passport No/FIN	GXXXX739P



Date Of Birth	02/11/1986
Occupation	Outdoor
Date Of Driving Pass	12/05/2015
Driving experience	6 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91219367
Alt. Phone Number	-
Email Address	laykeng.low@teeinfra.com
Address	41 DEFU LANE 1
Address complement	-
Postcode	539494
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	ABDUL AZIS BIN SUNOJO
Gender	Male

PASSENGER 2

Name	SA ADIN @ SA'ADIN BIN ISMAIL
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD4600Y
Vehicle Manufacturer	Nissan

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	VICKNESH S/O KANDASAMY
NRIC No	SXXXX100Z
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along AYE after South Buona Vista Rd Exit 8 & I was driving straight on Lane 3. out of sudden, I felt that there was an big impact & vehicle B was banged into rear portion of my vehicle & caused an accident.

I have video recording in my vehicle to prove that I was driving suddenly straight & his vehicle came and banged my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

☒ Policyholder's Signature
Date & Time:

☐ Driver's Signature
(If driver is not the policyholder)
Date & Time:

☐ Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GDRMC Sketchplan Form_V3


2







IMAGES #4



MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : EQ Insurance Company Ltd
 5 Maxwell Road #17-00 ,
 Towing Block MND Complex ,
 Singapore 069110

TEL: 6223 9433 FAX: 6224 3903
 ATTN: Motor Claim Department

Your Ref No: TEE ENVIRONMENTAL PL
 Claim Type: Third Party
 Accident Date: 04/01/2022
 TP Veh Reg No: GBD4600Y

Estimate No: ES1700980
 Date: 04 Jan 2022
 Policy No: 21-MJ001332-R03
 Veh Reg No: XB8691H
 Make/Model: SCANIA
 P360CB6X4MHZ
 Chassis No: YS2P6X40005429122
 Engine No: 6948461
 Reg. Date: 05/12/2016

Estimate Repair Cost to Vehicle No :XB8691H

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 Rear REL Rear Bumper	4,800.00	1 PC	4,800.00	
2 Rear REL Bin Hock	3,800.00	1 PC	3,800.00	
3 Rear REL Hock Hydraulic	1,200.00	2 PC	2,400.00	
4 Rear Signal Lamp RH	58.00	1 PC	58.00	
5 Rear Tail Lamp RH	68.00	1 PC	68.00	
6 Rear Reverse Lamp RH	58.00	1 PC	58.00	
			11,184.00	11,184.00
Labour				
7 Labour to renew rear REL rear bumper ,bin hock & hock hydraulic .	4,800.00	1 JOB	4,800.00	1000
8 Labour to reconnect wire for all lamp .	580.00	1 JOB	580.00	
9 To rust prrofig .	850.00	1 JOB	850.00	X
10 To spray & painting on affected area .	1,200.00	1 JOB	1,200.00	500
			7,430.00	7,430.00
Total			S\$ 18,614.00	
Add GST @ 7%			1,302.98	
Total Amount Payable			S\$ 19,916.98	

TOTAL: SINGAPORE DOLLAR NINETEEN THOUSAND NINE HUNDRED SIXTEEN AND CENTS NINETY EIGHT ONLY

For MAH LIAN MOTOR VEHICLE
 REPAIRER

not Authorised
 LKK
 12/1/22
 P/P \$ 1500
 3 days

LKK Auto Consultants hence notify
 the Repairer to provide the following:
AUTHORISED SIGNATURE
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: