PRS Filed By: GQ | REF: CS3/INC22000342/Gqy3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s ECO AUTO

of

Insured:

Policy No.

Claims No. MT/1157637-001

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJB686S Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN TOUAREG 3.6 c.c -

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 180568 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVGZZZ7PZBD027263 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R18

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CONTINENTAL

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	11-01-2022

Survey held at W/S 2:30

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$4000 - $5000
	No GIA provided
12/01/22	Submit PRS.

Date/Time, File Pass to? 1) 12/01 Typist

Date/Time, File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format: PRS

Lump Sum / UPD:

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL