

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |   |   |                 |       |                     |  |
|---|---|---|-----------------|-------|---------------------|--|
|   | CHINA TAIPING IN                        | ISURANCE (S) PTE LTD  |                 | Ref:  | CS/CTI22000358/Kty3 |  |
|   | 3 ANSON ROAD #<br>SPRINGLEAF TOV        | 16-00<br>VERSINGAPORE 079909  |                 | Date: | 11/01/2022          |  |
|   |   |   |                 | Code: | СТІ                 |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM |   |                 |       |                     |  |
|   | Insured Veh.                            | SMJ 5061J   | Veh. Inspected  |       | SME 482L            |  |
|   | Policy No.                              |   | Coverage (\$)   |       | 0.00                |  |
|   | Claim No.                               | SNM22D200205/C02/SMJ5061J<br>/CHNGPW  | Excess (\$)     |       | 0.00                |  |
|   | Assign From                             | ADELINE CHNG  | Assign Date     |       | 11/01/2022          |  |
| 2. Vehicle Particulars & Condition  |   |   |                 |       |                     |  |
|   | Make & Model                            |   | c.c             |       | 0                   |  |
|   | Engine No.                              | HIDDEN  | Year of Reg.    |       |                     |  |
|   | Chassis No.                             |   | Colour          |       |                     |  |
|   | Odometer                                | -   | Steering        |       |                     |  |
|   | Brakes                                  |   | Modification    |       |                     |  |
|   | General                                 |   |                 |       |                     |  |
| 3. Conditions of Tyres  |   |   |                 |       |                     |  |
|   |   | Size  | Make            |       | Balance             |  |
|   | R/H Front Tyre                          |   |                 |       | mm                  |  |
|   | L/H Front Tyre                          |   |                 |       | mm                  |  |
|   | R/H Rear Tyre                           |   |                 |       | mm                  |  |
|   | L/H Rear Tyre                           |   |                 |       | mm                  |  |
| 4.  | 4. Description of Damages               |   |                 |       |                     |  |
|   |   |   |                 |       |                     |  |
| 5. General Information  |   |   |                 |       |                     |  |
|   | Accident Date                           | 08/01/2022  | Inspection Date | е     | 12/01/2022          |  |
|   | Survey held at                          | ACCORD AUTO SERVICES PTE LTD  |                 |       |                     |  |
|   |   | 10 ANG MO KIO INDUSTRIAL PARK<br>2A AMK AUTO POINT #03-11<br>SINGAPORE 568047 |                 |       |                     |  |
| 5a. Remarks   |   |   |                 |       |                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |                 |       |                     |  |