

ComfortDelGro Engineering Pte Ltd

59 Loyang Drive Singapore 508969

	305501158	_
Our Ref	1 2 3 3 0 1100	

Time of Fax

Via Fax

Your Insured

Date of Acc

Attn: Motor Claims Department

Date

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

Chiang Liat Choon

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng Tel: 6214 8355 or HP: 9824 0811 ♦ Jumani Bin Masudin Tel: 6214 8315 or HP: 9635 5305 Lim Tien Siong Tel: 6214 8398 or HP: 9635 8546

limts@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

Tel: 6214 8314 or HP: 9296 6006

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE:

12-Jan-22

MODEL:

Toyota Prius

MVA: LIM T S

INSURANCE: LONPAC

VEHICLE NO.: SHA2258K

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Trunk Outer Garnish	1		\$889.70
	Rear Trunk Lid Logo (Prius)	1		\$60.80
	Rear Trunk Lid Logo (Hybrid)	1		\$52.40
	Rear Trunk Lid Logo (Toyota Star)	1		\$52.90
	Rear Bumper	1		\$458.60
1	Rear Bumper Re-Inforcement	1		\$318.80
	Rear Bumper Lower Cover-Black	1		\$552.60
1	Rear Bumper Ctr Under Cover	1		\$552.60
	Rear Bumper Side Retainer RH	1	\$112.70	\$112.70
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Reflector RH	1		\$55.00
	Rear Bumper Tow Cover	1		\$82.70
	Taillamp Upper RH	1	\$557.90	\$557.90
	Tailllamp Lower RH	1	\$548.40	\$548.40
	SUB TOTAL			\$4,317.10
	LESS 25%			\$1,079.28
	DISCOUNTED TOTAL			\$3,237.83
	Reverse Sensor	1		\$135.70
	Rear Trunk ComfortDelGro	1		\$30.00
	Rear Trunk 65521111	1		\$30.00
	Rear Trunk APPS	1		\$40.00
	NETT TOTAL			\$235.70
	TOTAL SPARE PARTS			\$3,473.53
	Labour Charge			40,110100
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$40.00
	Tuff Kote			\$40.00
	Remove/Refix Reverse Sensor			\$120.00
	10000			
	TOTAL LABOUR			\$1,600.00
	ESTIMATE TOTAL			\$5,073.53

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

SJ04221B000R / JP Knights Pte Ltd

ENTRY DATE & TIME: 11/01/2022 17:04 (SGT) SUBMITTED BY: Kavi VERSION: 1 (11/01/2022 17:04 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/01/2022 17:04 (SGT) Date of Accident 11/01/2022 08:00 (SGT) Exact Location of Accident Woodlands Cres, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA2258K

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD Company Reg No 1XXXXX821R Email Address fleetsafety@cdgtaxi.com.sg Mobile Phone No (Phone) +65-97365939 Alternative Phone No (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer

Toyota Model Prius Variant Exact purpose for which vehicle was being used at time of Private hire accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Taxi Transmission Auto CC 1798

INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd Type of Coverage ThirdPartyFireTheft Familian de la composición del composición de la composición de la composición de la composición de la composición del composición de la c Fleet Policy Yes Policy Number VFX/P2419138 Cover Note Number

DRIVER

Name of Driver LEE KIM AIK NRIC No SXXXX067C

Date Of Birth 27/08/1953 Occupation Outdoor Date Of Driving Pass 24/09/1973 Driving experience 48 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-97365939 Alt. Phone Number Email Address fleetsafety@cdgtaxi.com.sg Address 352A CANBERRA ROAD #11-263 Address complement Postcode 751352 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT

ON 11/01/2022 AT ABOUT 08:00HRS. I WAS DRIVING VEHICLE A, SHA2258K TRAVELLING ALONG WOODLANDS CRESENT WITHIN IN MY LANE, I WAS IN A STATIONARY POSITION WAITING FOR THE TRAFFIC LIGHT TURN INTO GREEN. SUDDENLY I FELT AN IMPACT COMING FROM MY REAR AND I REALISED VEHICLE B HAS REAR ENDED MY VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes

Reasons for not uploading a video of the accident FILE IS NOT SUITABLE

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

No

Vehicle Registration Number GBF1520D Vehicle Manufacturer Fiat Vehicle Model Doblo Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver SOUNDARRAJAN

Contact Number	<u> </u>
Address	2
Address complement	=
Postcode	2
Insurance Company Name	2
Nature Of Damage	2
Details of property damaged in accident	2
No, Of Passenger (Including Driver)	4

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

Lunderstand, acknowledge, agree and consent that:


- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the *Purposes*)
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Witnessed by Reporting Centre
Personnel MD NA 20 16

Sketch Plan



De

S	cribe Circumstances of the Accident
	ON 11/01/2022 AT ABOUT 08:00HRS. I WAS DRIVING VEHICLE A, SHA2258K TRAVELLING ALONG WOODLANDS CRESENT WITHIN IN MY LANE. I WAS IN A STATIONARY POSITION WAITING FOR THE TRAFFIC LIGHT TURN INTO GREEN. SUDDENLY I FELT AN IMPACT COMING FROM MY REAR AND I REALISED VEHICLE B HAS REAR ENDED MY VEHICLE.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Time

Driver's Signature (if driver is not the policyholder) / Date & Time 16:15 11.01.72

Witnessed by Reporting Centre Personnel MD NAZP-IN