



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: CYNTHIA LOH

Ref: CS3/ASM21010630/T1ty3e2-1  
Date: 08/03/2022  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	SHC 1878S	<b>Veh. Inspected</b>	SMT 6433K
<b>Policy No.</b>	VFX/P2419138	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S1M03K20	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CYNTHIA LOH	<b>Assign Date</b>	12/01/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA VEZEL HYBRID	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	RU31322398	<b>Colour</b>	RED
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	MICHELIN	6 mm
<b>L/H Front Tyre</b>	215/60 R16	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	215/60 R16	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	215/60 R16	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	11/10/2021	<b>Inspection Date</b>	17/01/2022
<b>Survey held at</b>	PROWERKZ GARAGE PTE LTD 25 KAKI BUKIT RD 4 #06-87 SYNERGY @ KB SINGAPORE 417800		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**