

ASS. REC. BY:

REF:

C72 / 220004761k

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PKV 59K

Yr Regn:

11, 18

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M.P. 5200

c.c.

1991

Colour

M.P. 5200

A/C:

Insured / Std / NI / NA

Sp. Reading

82934

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 2130422A 350383

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

9/1/22

D.O.I.

22/2/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S + RS. SI

Fines

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

# E M SOLUTION PTE LTD

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

## ESTIMATE

Date : 18th January 2022

Mr **Tan Pei Nam**  
9 Mt Sophia #02-28  
Singapore 228470

Veh No : **SKV 59K**  
Make/Model : **Mercedes E200 AVG**  
Chassis No : WDD2130422A550583  
Date of Acc : 09.01.22  
TP Veh No : SKS 5989J

S/No	Qty	Description	Unit Price	Amount
<b>Materials</b>				
1	1 pc	Frt Bumper		\$ 1,422.00 ✓
2	1 pc	Frt Bumper Side Holder RH		\$ 32.00 X
3	1 pc	Frt Bumper Garnish RH		\$ 90.00 2
4	2 pcs	PDC Parking Sensor	\$ 195.00	\$ 390.00 7
5	1 pc	Headlamp RH		\$ 3,780.00 7
				\$ 5,714.00
Less 10%				\$ 571.40
				\$ 5,142.60
6	1 set	Frt Bumper Clips (S/Nett)		\$ 60.00 ✓
Parts Total :				\$ 5,202.60
<b>Labour</b>				
1		To remove & rearrange electrical wirings, check lightings		\$ 100.00 201
2		To remove, repair & replace damaged bodyparts and where consistent to the accident.		\$ 400.00 2501
3		Putty and respray painting on affected portions.		\$ 500.00 2501
4		Rust proofing on affected portions.		\$ 100.00 X
5		Nano Coating		\$ 400.00 7
Labour Total :				\$ 1,500.00
Total Parts & Labour :				\$ 6,702.60

for E M Solution Pte Ltd

Not Withheld  
11 hrs &  
Money After Pay  
3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	10/01/2022 15:01 (SGT)
Date of Accident	09/01/2022 10:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ANG MO KIO ST 11 M/S CARPARK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SKV59K

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN PEI NAM
NRIC No	SXXXX918A
Email Address	TANJOHNNY0059@GMAIL.COM
Mobile Phone No	(Phone) +65-82898789
Alternative Phone No	+65-82898789

### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200 AVG (R18 LED)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991

### INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPG21013018
Cover Note Number	-

### DRIVER

Name of Driver	TAN JOHNNY
NRIC No	SXXXX072I

# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Tan Pei Han

Policyholder's Signature / Date & Time

W

Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel



Sketch Plan

A) SKV 59K  
B) SKS 5989J







**SINGAPORE  
POLICE FORCE**



T/20220110/2011

2 of 3

Report No. T/20220110/2011

Police Station Of Origin:  
Geylang N.P.C  
1 Cassia Link SINGAPORE 397618  
Tel No: 1800-8486999

**CONTINUATION OF REPORT**

<b>Driver</b>			
<b>Name</b>	TAN JOHNNY		<b>ID No.</b> S0171072I
<b>Related Vehicle</b>	SKV59K (Car)		<b>Contact No.</b> 82898789
<b>Hospital/Clinic</b>	NIL		<b>Class of Driving Licence &amp; Expiry Date</b> Class: 2B,2A,2,3 Date of Expiry: NIL
<b>Date Treatment</b>	NIL		<b>Date Discharge</b> NIL
<b>No. of Days granted Medical Leave</b>	NIL	<b>Degree of Injury</b>	NIL

**Brief Details.**

On 09/01/2022 at about 0830hrs, I parked my vehicle (SKV59K) Red Mercedes at a Multistorey carpark 104C Ang Mo Kio Street 11, Level 1 Lot 16, and went home.

At about 1430hrs, I drove my vehicle (SKV59K) Red Mercedes to my office at 11 Lorong 9 Geylang. One of my colleagues noticed that the right side of my vehicle has dents. I then checked the iRode camera in my car and noticed that at about 1053hrs, there was one vehicle (SKS5989J) Black Honda Vezel, which was parked next to my lot, bumped onto the right side of my vehicle as the driver of the said vehicle drove off. No particulars was given by the said driver.

I then came to Geylang NPC to lodge a traffic accident report for insurance claim purposes.