



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21012831/Rvf3e2-1	
			Date: 23/02/2022	
			Code: GRB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SNC 2169C	Veh. Inspected	SKR 8909B
	Policy No.	D21MFL0000447	Coverage (\$)	0.00
	Claim No.	MFL2021D0005532	Excess (\$)	0.00
	Assign From	CARINE KEK	Assign Date	11/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA VEZEL 1.5X AUTO	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	RU11013706	Colour	WHITE
	Odometer	137124 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	TRIANGLE	6 mm
	L/H Front Tyre	215/60 R16	TRIANGLE	6 mm
	R/H Rear Tyre	215/60 R16	TRIANGLE	6 mm
	L/H Rear Tyre	215/60 R16	TRIANGLE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/12/2021	Inspection Date	20/12/2021
	Survey held at	KOI MOTOR WORKS BLK 176 SIN MING DRIVE #04-12 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	