

REFERENCES

ASSIGNMENT

Veh No: SMV61841 Yr Regn: 2020 / Oct.

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit C.C. 1317

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 24281 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GR11001056 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R16

R: 205/50R16

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 12/01/22

Survey held at Twin Las.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

TP 111

MV:

PV :

Nett:

411E

☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

☐ : Site Insp (\$

□ Interview (\$)

Tech Inve (3)

Weekend 18

Survey Fee:

Transportation:

4 Photos

21. Others