





**SINGAPORE  
POLICE FORCE**



G/20211217/2113


2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20211217/2113

concrete debris found around my vehicle and on the roof of my vehicle. I then realized that there was a portion of the building surface structure that had collapsed. I assumed that it was due to the downpour earlier which had weakened the structure. A security guard was there and informed me that the building management staff had already left. He took some photographs of the damage caused by the fallen structure and gave me the contact details of the management (Name: Alexis, Tel:68442876). No one was injured. I am lodging this report for my own records and I will make a claim with the building management as the fallen pieces of debris had damaged the exterior of my vehicle.

Signature Of Officer Recording The Report: G / Sgt 3 TAN CHUAN SIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 17/12/2021 20:33
Officer In-Charge Of Case: G / Bedok Police Division Investigation Branch Insp (2) KHAJIF ADAM MALIK TIMBOEL MANIK	Classification Of Case:
Authentication Stamp  SIGNATURE	