

REC BY: Theravan | CS/FCI 22 000 \$33 / E 243

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
QD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. D21003447MFBP  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs. 1 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: XE 6577C Yr Rogn: 13/7/21  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Mercedes benz A10CS 2630 c.c. 7698  
Colour: grey A/C: \_\_\_\_\_ Insured / Std / NI / NA  
Sp. Reading: Not avail T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: W1T96401420S18246  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: NII / SIRIM / STD A/Rim or  
Tyre Size: F: 315/80R22.5  
R: 315/80R22.5  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 7 mm R/Bal. 7 mm  
L/Bal. 7 mm L/Bal. 7 mm  
D.O.A. 26/11/21 D.O.I. 9/2/22 1530  
Survey held at Sembwaste  
Des. of Damages: Fr Rear / O/S / N/S / U/C / Roof/Top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>F: 980.31</u>
08/03/22 @ 2.30pm	revised to FCI by email.
	Final fig \$980.31, 1 day (Red \$0/-, 0%)

Date/Time, File Pass to? ☐ : Prell. Report

08/03 Typist ☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 1

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Finibus

Others

Total

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Wash and

Request Form: TP

Final Fee: 980.31



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorized Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR XE6577C

SembWaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360

67233200A/C

## Vehicle & Document Information

WIP No 53141  
Reg No/Reg Date XE6577C / 13/07/2021  
Date In/Mileage 3412  
Chassis No W1T964014205182464  
Engine No 936912C0233465  
Make/Model MBCV/Arocs 2630 6X4 3900  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WS000458	Credit	03/12/2021/ 16:01	Gen	620 / Jaiganesh S

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
<b>THIS IS NOT AN OFFICIAL TAX INVOICE</b>				
Z. Customer concern (not cl)				
RH SIDE MIRROR QUOTE				
A 88323101			35.00	46.80
OUTSIDE MIRROR ON RIGHT REPLACE				
M MIRROR	1.00	1498.45	45.00	824.15
M COVER	1.00	92.26	45.00	50.74
M COVER	1.00	46.78	45.00	25.73
M COVER	1.00	44.73	45.00	24.60
M COVER	1.00	15.08	45.00	8.29

**ESTIMATE**

Thuan @Lkhauto.com  
82235769  
9/2/22 1530  
P/P 1 day wp

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Confirmed & accepted by

7% GST on **Nett 980.31** **980.31** **68.62**

**Total Payable 1,048.93**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: (65) 67714389  
Fax: (65) 67756310  
www.mercedes-benz.com.sg



ACCIDENT INVOLVING XE6577C AND SBS6450X ON 26.11.21



## Vehicle Registration Details

Vehicle No. <b>XE6577C</b>	Make/Model <b>MERCEDES BENZ /AROCS 2630 6X4 3900 (AUTO,ABS)</b>	Vehicle Scheme <b>-</b>
Current Propellant <b>Diesel</b>	Chassis No. <b>W1T96401420518246</b>	Vehicle Type <b>Goods (Open) Garbage /Sanitary Wagon</b>

## Owner's Details

Company Name:

**SEMBWASTE PTE. LTD.**

Registration ID:

**199507280G**

Registration Date:

**-**

Owner ID Type:

**Company**

Registered Address:

**30 HILL STREET #05-04 SINGAPORE 179360**

Birth Date:

**-**

## Registration Details

Registration ID:

**-**

Registration Date:

**13 Jul 2021**

Effective Date of Ownership:

**13 Jul 2021**

Registration Date:

**13 Jul 2021**

Type of Registration:

**0**

IU Label No:

**2010604765**

## Vehicle Specifications

Engine No:

**936912C0233465**

Chassis No:

**W1T96401420518246**

Year of Manufacture:

**2021**

Primary Colour:

**White**

Secondary Colour:

-

Passenger Capacity:

2

Engine Capacity / Power Rating:

7698 cc / -

Maximum Power Output:

-

Max Unladen Weight:

11440 kg

Maximum Laden Weight:

28000 kg

Vehicle Attachment 1:

With Roll On/Off

Vehicle Attachment 2:

-

Vehicle Attachment 3:

-

#### Additional Registration Fee (ARF) and COE Information

Open Market Value:

\$100,068.00

Additional Registration Fee Rate:

5.00 %

Actual ARF Paid:

\$5,004.00

Vehicle Lifespan Expiry Date:

12 Jul 2041

OPC Cash Rebate Eligibility:

No

QP during COE Bidding Exercise:

\$38,900.00

COE No.:

2021080105000002Z

COE Expiry Date:

12 Jul 2031

COE Category:

C - Goods Vehicle & Bus

COE Registration Category:

C - Goods Vehicle & Bus

Quota Premium (QP) / Prevailing Quota Premium:

\$38,900.00 / -

Actual QP Paid

\$38,900.00

QP (Regn Cat):

\$38,900.00

#### PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

Minimum PARF Benefit:

-

#### Vehicle Emissions Details



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	27/11/2021 17:01 (SGT)
Date of Accident	26/11/2021 15:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BEDOK NORTH ROAD TOWARDS JUNCTION OF BEDOK NORTH ROAD AND BEDOK RESERVOIR ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number XE6577C

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SEMBWASTE PTE LTD
Company Reg No	199507280G
Email Address	MOHAMAD.RANI@SEMBCORP.COM
Mobile Phone No	(Phone) +65-91864590
Alternative Phone No	+65-91864590

#### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	OTHERS
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	1656

#### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	5117487274-01
Cover Note Number	-

#### DRIVER

Name of Driver	TEH YU MENG
----------------	-------------

NRIC No	S2548787G
Date Of Birth	25/07/1966
Occupation	Outdoor
Date Of Driving Pass	21/10/1996
Driving experience	25 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-91836285
Alt. Phone Number	-
Email Address	MOHAMAD.RANI@SEMBBCORP.COM
Address	BLOCK 184C RIVERVALE CRESCENT #05-203
Address complement	-
Postcode	543184
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	ADVISED THE SUPERVISOR TO SEND TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBS6450X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	SIA KEE WEE



Work Permit No	4 04224107
Contact Number	(Phone) +65-83378645
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 27/11/2021  
 1900hrs

  
 Reporting Centre Personnel's Signature  
 Name: Low J. M.  
 NRIC/IN No: S994330

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A was stopped for waiting traffic light to turn green.

Vehicle B was travelling on right lane and collided onto front right mirror of vehicle A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 27/11/2021

Reporting Centre Personnel's Signature  
Name: Louis Lim  
NRIC/FIN No.: S974500