

REC BY: Thevan


REF: C61AIG2200571P53

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: GB320A6B Yr Rogn: 28/9/08  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota hiace c.c. 2986  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 259860 T/Radlo: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: STFHT02P70032245  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / SIRIm / STD AJRIm or \_\_\_\_\_  
 Tyre Size: F: 195R15C  
 R: 195R15C

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: 40k 47k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20. % 3 Val.: Yes or No



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Falken  
 Front R/Bal. 5 mm Rear R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 15/1/22 D.O.I. 17/1/22 1600  
 Survey held at Rydercar auto  
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Roof/tp or \_\_\_\_\_  
 The UIC / Chassis frame / Body Structure affected duo to collision.

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	MV: <u>40k 47k</u>
	rebate: <u>26417</u>
	NV: <u>13583 20583</u>
	BI
	F: <u>5500</u>
	RP: <u>7</u>

Date/Time File Pass to?  : Prelim. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trlp: \_\_\_\_\_

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Wheel end \_\_\_\_\_

Survey Fee:

Transportation:	_____ \$ + RS. _____ \$
Fuel/bus	_____
Others	_____
TOTAL	_____

Report Form: \_\_\_\_\_  
 Date/Time File Return to? \_\_\_\_\_