



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM22000580/Apa3q2 Date: 10/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7889X	Veh. Inspected	SMW 3636X
	Policy No.	P2419140	Coverage (\$)	0.00
	Claim No.	S1M03HQA	Excess (\$)	0.00
	Assign From		Assign Date	17/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS RX200T	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTJBAMCA202023900	Colour	BLACK
	Odometer	130635 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm
	L/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/09/2021	Inspection Date	18/01/2022
	Survey held at	VENTURES AUTO PTE LTD 23 KAKI BUKIT AVENUE 4, #04-01, AAS KAKI BUKIT CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	