

ASS. REC. BY:

REF:

C72 / 22000583 / 144

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FB14 73314

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha YBR

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

40000

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LBPK81782D 001430

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Golden Boy 80 / 190 R18

R: Shinko 3.60 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

8 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/11/21

D.O.I.

17/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
Email: yeeautopte ltd@gmail.com  
Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 30/11/2021  
TP Veh Reg No: GBL3411R

Estimate No: ES2100123

Date: 17 Jan 2022

Policy No:

Veh Reg No:

Make/Model: YAMAHA YBR 125  
MANUAL

Chassis No: LBPKE1782D0014326

Engine No: E3J2E008837

Reg. Date: 11/09/2013

## Estimate Repair Cost to Vehicle No :FBH7331H

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT NUMBER PLATE	45.00	1 PC	45.00	45.00
Spare Parts				
2 BRAKE LEVER	68.00	1 PC	68.00	X
3 CLUTCH LEVER	68.00	1 PC	68.00	X
4 GEAR PEDAL	90.20	1 PC	90.20	X
5 FORK OIL SEAL - LH	38.00	1 PC	38.00	—
6 FORK OIL SEAL - RH	38.00	1 PC	38.00	—
7 FRONT FAIRING - LH	288.00	1 PC	288.00	X
8 FRONT FAIRING - RH	288.00	1 PC	288.00	X
9 FRONT FORK - LH	386.00	1 PC	386.00	—
10 FRONT FORK - RH	386.00	1 PC	386.00	—
11 FRONT FORK TUBE - LH	222.00	1 PC	222.00	—
12 FRONT FORK TUBE - RH	222.00	1 PC	222.00	—
13 FRONT WHEEL BEARING	28.00	1 PC	28.00	X
14 FRONT WHEEL RIM FENDER	198.00	1 PC	198.00	X
15 FRONT HANDLE BAR HOLDER BEARING - TOP	85.00	1 PC	85.00	X
16 FRONT HANDLE BAR HOLDER BEARING - LOWER	85.00	1 PC	85.00	X
17 FRONT HANDLE BAR	105.20	1 PC	105.20	—
18 FRONT SIGNAL LAMP - LH	125.10	1 PC	125.10	—
19 FRONT HEADLAMP COVER - CENTRE	288.00	1 PC	288.00	—
20 LOWER STEP BAR	105.10	1 PC	105.10	X
21 FRONT FORK HOLDER BRACKER	380.00	1 PC	380.00	?
22 FRONT COWLING - LH	165.00	1 PC	165.00	—
23 HANDLE RUBBER - LH	38.00	1 PC	38.00	X
24 HANDLE RUBBER - RH	38.00	1 PC	38.00	X
25 FRONT COWLING - RH	165.00	1 PC	165.00	X
26 FRONT WHEEL BEARING	45.00	1 PC	45.00	X
27 HEAD LAMP	480.00	1 PC	480.00	—
28 SPEED METER	785.00	1 PC	785.00	X
29 SIDE STAND RUBBER - LH	65.00	1 PC	65.00	X
30 SIDE STAND RUBBER - RH	65.00	1 PC	65.00	X
31 WING MIRROR - LH	144.00	1 PC	144.00	X
32 HANDLE BAR BRACKET	180.00	1 PC	180.00	?
33 REAR BOX	195.00	1 PC	195.00	X





# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 30/11/2021  
TP Veh Reg No: GBL3411R

Estimate No: ES2100123  
Date: 17 Jan 2022  
Policy No:  
Veh Reg No: FBH7331H  
Make/Model: YAMAHA YBR 125  
MANUAL  
Chassis No: LBPKE1782D0014326  
Engine No: E3J2E008837  
Reg. Date: 11/09/2013

## Estimate Repair Cost to Vehicle No :FBH7331H

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			5,858.60	5,858.60
<b>Labour</b>				
34 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	500.00	1 JOB	500.00	1501
35 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	500.00	1 JOB	500.00	X
36 TO ALIGN MAIN BODY FRAME.	300.00	1 JOB	300.00	1001
37 TO TOW VEHICLE TO WORKSHOP.	60.00	1 JOB	60.00	301
			1,360.00	1,360.00

Total S\$ 7,263.60

Add GST @ 7% 508.45

Total Amount Payable S\$ 7,772.05

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SEVEN HUNDRED SEVENTY TWO AND CENTS FIVE ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE



**SINGAPORE  
POLICE FORCE**



T/20211130/2115

Police Station Of Origin:  
Geylang N.P.C  
1 Cassia Link SINGAPORE 397618  
Tel No: 1800-8486999

1 of 3

Report No. T/20211130/2115

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 30/11/2021 22:48		Vide Report No.: G/20211130/0101		Station Diary No.: 91	
<b>Informant's Particulars</b>					
Name of Informant: ISMAIL THAMBI MOHAMED BATHURUDEEN			Address: APT BLK 474 CHOA CHU KANG AVENUE 3 #13-197 SINGAPORE 680474		
ID Type / ID No.: FIN NO / G6358304P			Contact No.: Home/Office: Mobile: 82960757		
Nationality: INDIAN			Email: bathu87@gmail.com		
Sex: Male	Age: 34	Date of Birth: 17/05/1987	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Engineer			Driving Licence Information: Class: 2B Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/11/2021 11:30	Type of Location: Straight Road
Location:  JALAN SENANG				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH7331H	Motorcycle				Slightly Damaged	0
GBL3411R	Van				Slightly Damaged	0





**SINGAPORE  
POLICE FORCE**



T/20211130/2115

Police Station Of Origin:  
Geylang N.P.C  
1 Cassia Link SINGAPORE 397618  
Tel No: 1800-8486999

2 of 3

Report No. T/20211130/2115

**CONTINUATION OF REPORT**

**Brief Details.**

On 30/11/2021 at 1130hrs, I was riding my blue yamaha motorbike (FBH7331H) travelling along Jalan Senang there was a Grey Nissan van(GBL3411R) which parked on the left close to the white line. From a far distance, I saw his van was stationary. However when I ride closer the van came out and collided with me. My front left motorbike was slightly damaged.

At that point of time there was no traffic light as it was near a residential estate and the weather was clear and sunny.

I did not exchange any particulars with the van driver.

When I collided with the van I was conscious however I had a cut at my nose, my upper lip area and forehead area.

The traffic police and ambulance came and assist me and took the van driver particulars and took an sd card from the driver.

I was then conveyed to CGH and got a Medical certificate covered.

I am using this report for my insurance.