

ASS. REC. BY:

REF:

ASM/ 220003881ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16-18 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 63415 Yr Regn: 06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

cc

1496

Colour

M. Black

AC:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

G/A No:

GP7 - 12074PS

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / PS/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

13/1/22

D.O.I.

17/1/2022

Survey held at

Des. of Damages (Fit) Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ Broken Sign

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fares

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Not Authorized
 L1 Ry 8
 Penny After Pain
 16 days

VEHICLE NO: SMA6341S

MODEL: HONDA SHUTTLE

CHASSIS NO: GP7-1207495

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
PARTS (LIST ITEMS)	
FRONT BUMPER	B/Hn \$ 1,210.00
FRONT BUMPER RETAINER LHS	CM \$ 30.00
FRONT BUMPER RETAINER RHS	CM \$ 30.00
FRONT FOG LAMP LHS	M/S \$ 310.00
FRONT FOG LAMP RHS	Sn \$ 310.00
FRONT FOG LAMP COVER LHS	M/S \$ 70.00
FRONT FOG LAMP COVER RHS	Rn \$ 70.00
FRONT BUMPER LOWER COVER	CM \$ 200.00
FRONT BUMPER LOWER GRILLE	CM \$ 120.00
FRONT GRILLE	CM \$ 410.00
FRONT GRILLE OUTER GARNISH (CHROME)	CM \$ 300.00
FRONT GRILLE LOWER GARNISH (CHROME)	CM \$ 230.00
FRONT GRILLE CENTRE BRACKET	\$ Rn 90.00
FRONT EMBLEM	Rn \$ 40.00
HEADLAMP LHS	CM \$ 2,320.00
HEADLAMP RHS	my D/S \$ 2,320.00
HEADLAMP BRACKET LHS	\$ CM 60.00
HEADLAMP BRACKET RHS	\$ Sn 60.00
FRONT REINFORCEMENT	Rn \$ 330.00
SUPPORT PANEL	Rn \$ 680.00
FRONT WHEELHOUSE LHS	Rn \$ 510.00
FRONT WHEELHOUSE RHS	Rn \$ 510.00
FRONT WHEELHOUSE EXTENSION LHS	\$ Rn 200.00
FRONT WHEELHOUSE EXTENDER RHS	\$ Rn 200.00
FRONT FENDER LHS	Rn \$ 460.00
FRONT FENDER RHS	Rn \$ 460.00
FRONT FENDER INNER SHIELD LHS	Tn \$ 120.00
FRONT FENDER INNER SHIELD RHS	CM \$ 120.00
FRONT BONNET	Rn \$ 720.00
FRONT BONNET HINGE LHS	\$ Rn 50.00
FRONT BONNET HINGE RHS	\$ Rn 50.00
FRONT BONNET LOCK ASSY	\$ Rn 200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FRONT BONNET INSULATION
 FRONT BONNET RUBBER TRIM
 FRONT BONNET AIR GUIDE
 WIPER COWL
 FRONT QUARTER GLASS LHS
 FRONT QUARTER GLASS MOULDING LHS
 WIPER RESERVOIR
 CONDENSER
 RADIATOR
 RADIATOR CROWNING
 RADIATOR FAN BLADE
 RADIATOR FAN MOTOR
 LIQUID PIPE
 SUCTION PIPE
 DISCHARGE PIPE
 INTAKE MANIFOLD
 DASHBOARD
 CLOCK SPRING
 DRIVER'S AIRBAG
 PASSENGER AIRBAG
 AIRBAG CONTROL UNIT
 FRONT SEAT BELT ASSY LHS
 FRONT SEAT BELT ASSY RHS
 FRONT SEAT LHS
 FRONT SEAT RAILINGS LHS
 FRONT WINDSCREEN
 FRONT WINDSCREEN MOULDING
 HORN

<i>refurb</i>	\$	180.00	1
<i>cu</i>	\$	40.00	1
<i>cm</i>	\$	120.00	1
<i>neu</i>	\$	300.00	1
<i>phantom</i>	\$	300.00	1
<i>ru</i>	\$	120.00	1
<i>pu</i>	\$	100.00	X
<i>By</i>	\$	850.00	1
<i>pu/By</i>	\$	1,350.00	1
	\$	150.00	7
	\$	80.00	7
	\$	320.00	7
	\$	230.00	7
	\$	300.00	7
	\$	280.00	7
	\$	460.00	7
<i>Tu</i>	\$	1,260.00	1
<i>ru</i>	\$	360.00	1
<i>Burn</i>	\$	1,640.00	1
<i>u</i>	\$	2,240.00	1
<i>ru</i>	\$	970.00	1
<i>Tu</i>	\$	680.00	1
<i>Tu</i>	\$	680.00	1
<i>R</i>	\$	2,960.00	7
	\$	850.00	7
<i>cm</i>	\$	1,820.00	1
<i>ru</i>	\$	60.00	1
	\$	120.00	7

	\$ 31,610.00
10%	\$ 3,161.00
	\$ 28,449.00

SPECIAL NETT ITEMS

FRONT SENSORS
 FRONT CARPLATE W/HOLDER
 FRONT BUMPER CLIPS
 WINDSCREEN SEALANT
 CEREMIC COATING

	\$	200.00	7
	\$	60.00	45m
	\$	40.00	1
	\$	50.00	40m
(Bill)	\$	750.00	?

Total	\$ 1,100.00
-------	-------------

TOTAL PARTS	\$ 29,549.00
-------------	--------------

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)
	LABOUR	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 2,500.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 2,500.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00
4	To provide anti-rust treatment on affected areas	\$ 100.00
5	Remove & refit front sensor	\$ 100.00
6	Dignostic Check	\$ 100.00
7	Remove & refit engine	\$ 400.00
8	Remove & refit dashboard	\$ 300.00
	Labour Total :	\$ 6,100.00
	TOTAL (PARTS & LABOUR):	\$ 35,649.00

12001

14001

301

✓

X

7

2501

2501

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers or the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/01/2022 15:12 (SGT)
Date of Accident	13/01/2022 07:45 (SGT)
Exact Location of Accident	Tuas South Ave 3, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA6341S
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Lian Kuek Kien
NRIC No	S1723805A
Email Address	williamlian65@gmail.com
Mobile Phone No	(Phone) +65-94380052
Alternative Phone No	(Home) +65-94380052

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5124405326
Cover Note Number	-

DRIVER

Name of Driver	Lian Kuek Kien
NRIC No	S1723805A

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts will allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- (ii) investigating the accident and/or my claims
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/small packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Tuas South Avenue 3

Vehicle A - SMD 534 S

Vehicle B - SFD 716 M

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	805A
Vehicle Details	
Vehicle No.:	SMA6341S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jan 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	LEB6549220
Chassis No.:	GP71207495
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,364.00
Original Registration Date:	14 Jun 2018
First Registration Date:	14 Jun 2018
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2028
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,700.00
COE Rebate Amount:	\$24,339.00
Total Rebate Amount:	\$28,089.00

The information contained herein is correct as at 17 Jan 2022

OK