

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22000615/Aqf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	[Date:	24/05/2022	
			C	Code:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLX 9819C	Veh. Inspected		SMM 1626R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10013401/JM	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		18/01/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KMHD841CMKU906699	Colour		SILVER	
	Odometer	46670 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	FALKEN		6 mm	
	L/H Front Tyre	195/65 R15	FALKEN		6 mm	
	R/H Rear Tyre	195/65 R15	FALKEN		6 mm	
	L/H Rear Tyre	195/65 R15	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/01/2022	Inspection Date		24/01/2022	
	Survey held at	HD PERFECT AUTOWORK PTE LTD				
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
			. y = 11 110 pm			

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: