

ASS. REC. BY: Tauph

REF:

CC3/ Tm 22000629/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMS 378G

Policy No. MR000568

Claims No. M2200334

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: Lim TS Vehicle: IN / OUT

Veh No: SHA2258K Yr Regn: 2020, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 188947 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JD DK B3 F4 303091262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or wirelike

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/1/2022 D.O.I. 14/1/22

Survey held at Compt Loyang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/2/22	Final fig \$6972.50 (red 360.02, 5%)

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?
2) 8/2/22-typist

Rep. Format: Merimen

Lump Sum / L.B.I. : \$6972.50

Days Of Repair: 2
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS. \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

SAS-KIV

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

CP/P

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/01/2022
Vehicle Reg. No.:	SHA2258K	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	15/04/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2G76594	Chassis No:	JTDKB3FU30309126
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

Amount

Parts	1,211.72
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,042.72
+ GST 7.00% (S\$)	142.99
Nett Amount (S\$)	2,185.71

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Jan 2022)**Parts:** 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA2258K/14/01/2022 14:05**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	de *458.60 FL
2	1		*REAR BUMPER CTR MOULDING	25.00	0.00	de *552.60 FL
3	1		*REAR BUMPER TOW COVER	25.00	0.00	ms *82.70 FL
4	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	? *318.80 FL
5	10		*REAR BUMPER CLIPS	25.00	0.00	ms *22.00 FL
6	1		*REVERSE SENSORS	0.00	0.00	ms *135.70 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 1,570.40**- List Item Discount on L Items (S\$)** 358.68**Total Parts (S\$)** 1,211.72**ComfortDelGro Engineering Pte Ltd/SHA2258K/14/01/2022 14:05.** Not valid without Reference section.Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 400.00
2	SPRAY PAINTING	New	250 300.00
3	R/I REVERSE SENSORS	New	30 120.00
Gross Labour Cost (S\$)			820.00

ComfortDelGro Engineering Pte Ltd/SHA2258K/14/01/2022 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfah 97495749
'wp' 14/1/22 4pm
P/P Body knife paint
Tanfah @ 1600000000
- 2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 14.01.2022 13:33

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4163262

JC NO 305501524

OMER

S

COMFORT TRANSPORTATION PTE LTD

OMER NO.

7010045

ESS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

DUNT CARD NO.

REGN NO.

SHA2258K

MILEAGE

MAKE

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A14.01.2022 12:05

DATE/TIME IN

YR OF MANU

15.04.2020

TARGET DATE

CHASSIS CODE

JTDKB3FU303091262

COMPLETION DATE/TIME:

cident Date: 14.01.2022

TURE: 3P 14.01.2022

JOB DESCRIPTION

NO


0010

LABOR CODE

PB

DESCRIPTION

PANEL BEATING-SHA2258K



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Jo:

SHA2258K

LIMITS

Vehicle No.:

SHA2258K

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard