

1 of 2 ?

100%

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                    |                                                                        |                 |                          |  |
|--------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|-----------------|--------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile                                                  |                                                                        |                 |                          |  |
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                 |                                                                        |                 | Ref: CS/AIG22000635/Eqf3 |  |
| 78 SHENTON WAY #09-16                                                                                              |                                                                        |                 | Date: 18/01/2022         |  |
| AIG BUILDING                                                                                                       |                                                                        |                 |                          |  |
| SINGAPORE 079120                                                                                                   |                                                                        |                 | Code: AIG                |  |
| 1. Policy Particulars :- OWN DAMAGE                                                                                |                                                                        |                 |                          |  |
| Insured Veh.                                                                                                       | Veh. Inspected                                                         |                 | SCA 7876C                |  |
| Policy No.                                                                                                         | 1800018600                                                             | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                          | Excess (\$)                                                            |                 | 0.00                     |  |
| Assign From                                                                                                        | CHIN LEE YING                                                          | Assign Date     | 18/01/2022               |  |
| 2. Vehicle Particulars & Condition                                                                                 |                                                                        |                 |                          |  |
| Make & Model                                                                                                       | c.c                                                                    |                 | 0                        |  |
| Engine No.                                                                                                         | HIDDEN                                                                 | Year of Reg.    |                          |  |
| Chassis No.                                                                                                        | Colour                                                                 |                 |                          |  |
| Odometer                                                                                                           | -                                                                      | Steering        |                          |  |
| Brakes                                                                                                             | Modification                                                           |                 |                          |  |
| General                                                                                                            |                                                                        |                 |                          |  |
| 3. Conditions of Tyres                                                                                             |                                                                        |                 |                          |  |
|                                                                                                                    | Size                                                                   | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                     |                                                                        |                 | mm                       |  |
| L/H Front Tyre                                                                                                     |                                                                        |                 | mm                       |  |
| R/H Rear Tyre                                                                                                      |                                                                        |                 | mm                       |  |
| L/H Rear Tyre                                                                                                      |                                                                        |                 | mm                       |  |
| 4. Description of Damages                                                                                          |                                                                        |                 |                          |  |
|                                                                                                                    |                                                                        |                 |                          |  |
| 5. General Information                                                                                             |                                                                        |                 |                          |  |
| Accident Date                                                                                                      | 17/01/2022                                                             | Inspection Date | 18/01/2022               |  |
| Survey held at                                                                                                     | CYCLE & CARRIAGE KIA PTE LTD<br>209 PANDAN GARDENS<br>SINGAPORE 609339 |                 |                          |  |
| 5a. Remarks                                                                                                        |                                                                        |                 |                          |  |
| A)THE MARKET VALUE IS S\$------(EST. AVERAGE)<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |                                                                        |                 |                          |  |