

ASS. REC. BY: Steve

REF:

CS/AIG 22000637/ETF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|----------------|----------------|
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMJ 4963M Yr Regn: 8/3/19Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato c.c. 1591Colour: Red A/C: Insured / Std / NI / NASp. Reading: 28593 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF3416MK503.1070Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModl: ☒ Nil / S/Rlm / STD A/Rlm orTyre Size: F: 225/45R17R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO orFront R/Bal. 5 mmL/Bal. 5 mmD.O.A. 18/1/22

Survey held at

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-69K

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info | |
|--|---------------------------|----------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name | /DESMOND TAN JUN YUAN |
| | Reg No/Reg Date | SMJ4963M*KC17/ 08/03/201 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNAF3416MK5031070 |
| | Engine No | G4FGJH722036 |
| | Make/Model | KIA/CERATO 1.6 A SR SX G335 |
| | Colour/Trim | CR5 RUNWAY RED / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---|--------|-------------------|-----|-------------------|--------|------------|-------|---------|
| LAX00000 | Credit | 18/01/2022/ 12:56 | BLE | 261 / Edwin Caina | 45746 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | 3200.00 |
| RENEW FR BUMPER , FR SUPPORT , BONNET , LHF FENDER & RHF FENDER 5 x 499 | | | | | | | | 2000 |
| REPAIR LHF DOOR , RHF DOOR & FR A PILLAR LH/RH | | | | | | | | |
| E PNT98000 | | | | | | | | 3840.00 |
| RESPRAY FR BUMPER , BONNET , LHF FENDER , RHF FENDER , 480 (CR5) x 5 | | | | | | | | 2400 |
| LHF DOOR , RHF DOOR & FR A PILLAR LH/RH | | | | | | | | |
| E PNT88000 | | | | | | | | 100.00 |
| REMOVE & REFIT AC COND & RADIATOR | | | | | | | | |
| M SUNDRY | | | | | | | | 80.00 |
| TOP UP AC GAS | | | | | | | | |
| A 54900099 | | | | | | | | 30.00 |
| CHECK WIRING ELECTRICAL SYSTEM | | | | | | | | |
| A 10028901 | | | | | | | | 120.00 |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | | |
| M SUNDRY | | | | | | | | 50.00 |
| SUPPLY FR NUMBER PLATE WITH CASING BR | | | | | | | | |
| M SUNDRY | | | | | | | | 120.00 |
| APPLY ANTI CORROSION ON AFFECTED AREAS | | | | | | | | 40 |
| M SUNDRY | | | | | | | | 80.00 |
| SUPPLY BODY PNL SEALANT | | | | | | | | 40 |
| M SUNDRY | | | | | | | | 20.00 |
| Sundries | | | | | | | | |
| M COVER-FR BUMPER | BR | | | | 1.00 | 633.00 | 20.00 | 506.40 |
| M GRILLE-FRONT BUMPER | CUT | | | | 1.00 | 485.00 | 20.00 | 388.00 |
| M GRILLE ASSY-RADIATOR | BR | | | | 1.00 | 328.00 | 20.00 | 262.40 |
| M GARNISH-RADIATOR GRILLE | BR | | | | 1.00 | 38.00 | 20.00 | 30.40 |
| M MOULDING-FRONT BUMPER,LH | CUT | | | | 1.00 | 216.00 | 20.00 | 172.80 |
| M MOULDING-FRONT BUMPER,RH | CUT | | | | 1.00 | 216.00 | 20.00 | 172.80 |
| M LAMP ASSY-SIDE REPEATER,LH | ? | | | | 1.00 | 143.00 | 20.00 | 114.40 |
| M LAMP ASSY-SIDE REPEATER,RH | ? | | | | 1.00 | 143.00 | 20.00 | 114.40 |
| M ABSORBER-FRONT BUMPER ENERGY | BR | | | | 1.00 | 84.00 | 20.00 | 67.20 |
| M STIFFNER-FR BPR LWR | ? | | | | 1.00 | 114.00 | 20.00 | 91.20 |
| M BRACKET-FR BUMPER UPR SIDE MTG | ? | | | | 1.00 | 22.00 | 20.00 | 17.60 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name /DESMOND TAN JUN YUAN Reg No/Reg Date SMJ4963M*KC17/ 08/03/201 Date In/Mileage / 0 Chassis No KNAF3416MK5031070 Engine No G4FGJH722036 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|--------------------------------|-------------------|-----|-------------------|--------|------------|-------|---------|
| LAX00000 | Credit | 18/01/2022/ 12:56 | BLE | 261 / Edwin Caina | 45746 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | BRACKET-FR BUMPER UPR SIDE MTG | | | | 1.00 | 22.00 | 20.00 | 17.60 |
| M | WIRING ASSY-BUMPER EXTENSION | | | | 1.00 | 207.00 | 20.00 | 165.60 |
| M | ULTRASONIC SENSOR ASSY-P.A.S | | | | 4.00 | 163.00 | 20.00 | 521.60 |
| M | ORNAMENT-KIA NO.115 | | | | 1.00 | 32.00 | 20.00 | 25.60 |
| M | BEAM COMPLETE-FR BUMPER | | | | 1.00 | 497.00 | 20.00 | 397.60 |
| M | CARRIER ASSY-FRONT END MODULE | | | | 1.00 | 675.00 | 20.00 | 540.00 |
| M | PANEL ASSY-HOOD | | | | 1.00 | 1502.00 | 20.00 | 1201.60 |
| M | HINGE ASSY-HOOD,LH | | | | 1.00 | 43.00 | 20.00 | 34.40 |
| M | HINGE ASSY-HOOD,RH | | | | 1.00 | 43.00 | 20.00 | 34.40 |
| M | PANEL-FENDER,LH | | | | 1.00 | 430.00 | 20.00 | 344.00 |
| M | PANEL-FENDER,RH | | | | 1.00 | 430.00 | 20.00 | 344.00 |
| M | PAD-HOOD INSULATING | | | | 1.00 | 156.00 | 20.00 | 124.80 |
| M | CLIP-HOOD INSULATING PAD MTG | | | | 13.00 | 1.00 | 20.00 | 10.40 |
| M | LATCH ASSY-HOOD | | | | 1.00 | 103.00 | 20.00 | 82.40 |
| M | LAMP ASSY-HEAD,LH | | | | 1.00 | 2210.00 | 20.00 | 1768.00 |
| M | LAMP ASSY-HEAD,RH | | | | 1.00 | 2210.00 | 20.00 | 1768.00 |
| M | GUARD-AIR,LH | | | | 1.00 | 28.00 | 20.00 | 22.40 |
| M | GUARD-AIR,RH | | | | 1.00 | 28.00 | 20.00 | 22.40 |
| M | CONDENSER ASSY-COOLER | | | | 1.00 | 687.00 | 20.00 | 549.60 |
| M | RADIATOR ASSY | | | | 1.00 | 646.00 | 20.00 | 516.80 |
| M | BLOWER ASSY | | | | 1.00 | 656.00 | 20.00 | 524.80 |
| M | GUARD ASSY-FRONT WHEEL,LH | | | | 1.00 | 95.00 | 20.00 | 76.00 |
| M | GUARD ASSY-FRONT WHEEL,RH | | | | 1.00 | 95.00 | 20.00 | 76.00 |

SURVEYOR NAME: Steve (LKK) 18/1/22, 3:30pm
 SURVEYOR SIGNATURE: OD-MML
 DATE: EX-11-?
 REMARKS: PIP, My BL y

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7 djs

| | |
|----------------------|------------------|
| Nett | 18,745.60 |
| 7% GST on | 1312.19 |
| Total Payable | 20,057.79 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/01/2022 12:45 (SGT)
Date of Accident 18/01/2022 10:15 (SGT)
Exact Location of Accident TPE, Singapore
Additional Location Information TPE NEAR KPE EXIT
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ4963M

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner DESMOND TAN JUN YUAN
NRIC No SXXXX804Z
Email Address Desmondtan_1989@hotmail.com
Mobile Phone No (Phone) +65-91820984
Alternative Phone No +65-91820984

VEHICLE PARTICULARS

Manufacturer Kia
Model Cerato
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1591

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1900017590-01
Cover Note Number -

DRIVER

Date of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode

16/08/1989
Indoor
25/11/2008
13 YEARS AND 2 MONTHS
Male
(Phone) +65-91820984
+65-91820984
Desmondtan_1989@hotmail.com
BLK. 289A COMPASSVALE CRESCENT
#06-301 SINGAPORE
541289
Yes
-
No
-
-

Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes
Was there any audio recorded? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD1693Z
Vehicle Manufacturer Toyota
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Commercial vehicle
Name of Driver LIM WEI YAP
Contact Number (Phone) +65-93283511
Address

Insurance Company Name
Amount Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

11.37am
18/1/22
Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

A lot of cars lining up along TPE, to exit towards KPE. My car came to a stationary to wait for cars in front to move. Cars in front started to move, I proceed to move the car as well. Very shabby, van (GBL 6233T) came to an abrupt stop, I tried to brake hard as well, but could not avoid the hit onto the van in front. GBL 6233T seems to be trying to jam brake to avoid (GBL 6233T) another van in front but failed to do so. According to driver of GBL 6233T, he was trying to brake hard to avoid the car in front of him, hence the sudden brake. There was a lorry behind me which just managed to avoid ~~my~~ my car as well. Took photos and exchange contacts with parties involved before leaving the scene.

Declaration

We declare the foregoing particulars are true in every respect.

11:40am



18/1/22

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : DESMOND TAN JUN YUAN
Period of Insurance : 08 Mar 2021 To 07 Mar 2022
Engine No. : G4FGJH722036
Chassis No. : KNAF3416MK5031070

Vehicle No. : SMJ4963M
Policy No. : 1900017590-01
Endorsement No. :
Issued Date : 26 Feb 2021

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAFF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Mileage Condition : Unlimited Mileage

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

DESMOND TAN JUN YUAN - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622222

C&CKICP2 - WINYEO

239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBILEAPP