

ASS. REC. BY:

REF:

072/ 22 000639/Kv y3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLZ 2167K

Policy No. DMPCSNW00058662402

Claims No. SNM22D200412/C02/LEEPG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

21/3/22 Kenneth informed \$1306.86 (Red 670.40, 33%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

22/3/22-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I: (\$ 1306.86)

Veh No:

SMU 50894 Yr Regn: 08, 2.0

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV c.c. 1496

Colour

n. Black A/C: Insured / Std / NI / NA

Sp. Reading

20288 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

THMRUR 1810JX 208701

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

17/1/22

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.

21/1/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 045713
Date calculated: 17/01/2022 5:35 PM

Full Report
Registration: SMU5089Y
Printed: 17/01/2022 5:36 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	17/01/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	HR-V RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 09
Registration:	SMU5089Y
VIN number:	
Odometer:	

Model Specs

TWO COAT METALLIC PREPARE OFF VEHICLE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	WU	Price SGD
8111A5	RENEW REAR BUMPER INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.	7.0		7.0	29.40
823100	RENEW TAILGATE INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	32.0		32.0	134.40
8231C2)	R + R MANUFACTURER BADGE	1.0		1.0	4.20
Labour Cost		Hrs	WU		
Panel / Mechanical Labour		4.00	40.0		168.00
Total of Labour					168.00

Not Arrived
Resurvey B4 paint
4 days

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BOOTLID/TAILGATE NEW PART PAINTING	19.0	

Paint Material Per Part

Code	Description	Price SGD
2931	BOOTLID/TAILGATE NEW PART PAINTING	59.86

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			19.0	
Preparation Main Work Metal		2.50	25.0	105.00
Total	10 WU/h	4.40	44.0	184.80

Material Cost - Paint

	Price SGD
New Part Painting	59.86
Material-constant Metal Preparation	28.60
Total	88.46

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER	71501T8NT00	Original		180.00 ?
2931	BOOTLID/TAILGATE	68100T8PU00ZZ	Original		530.00 ✓
2977	BOOT/TAILGATE LOCK	74800T7AH01	Original	RM	120.00 X
3015	MANUFACTURER BADGE	75701T5A000	Original	RM	10.00 ✓
3017	BADGE MODEL	75722T7WA01	Original	RM	12.00 ✓
3019	ENGINE BADGE	75725T8NT00	Original	RM	12.00 X
3163	REAR SCREEN FIX SET	USE SINGLE PARTS			
3170	CHECK	91502S70003			0.00
3171	CHECK	91501S70003			0.00
3173	CHECK	91536SS0J01			0.00
3284	R/R INNER LAMP	34150T7SA01	Original	RM	200.00 X
4907	INNER TAILGATE TRIM	84431T8NT01ZA	Original	RM	110.00 X
1000	TAILGATE CHROME TRIM TAILGATE		Original	RM	180.00 X
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				1,354.00
u: Used parts	Fixed Sundry Parts Price				10.00
	Total				1,364.00

Extras

Code	Description	Price SGD
1001	RR W/S SEALANT REAR WINDSCREEN	40.00* ✓

Code	Description	Price SGD
1002	RR W/S INNER SEAL REAR WINDSCREEN	<i>m</i> 27.00*
1003	Electrical work Electrical work	<i>15/</i> 25.00*
1004	TUFF KOTE TUFF KOTE	<i>30/</i> 80.00*
	Total Extras	172.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	1,354.00	
Total Parts	10.00	1,364.00
Labour Time Base 10 WU/h		
Total 40.0 WU X 42.00 SGD/h	168.00	
Total of Labour		168.00
Total Of Extras		172.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 42.00 SGD/h	184.80	
Material Cost	88.46	
Total Paint Including Material		273.26
Repair Cost Excludes GST		1,977.26
GST (+7.0%)		138.41
Repair Cost Included GST		2,115.67

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 17/01/2022 11:19 (SGT)
Date of Accident 17/01/2022 07:10 (SGT)
Exact Location of Accident Ang Mo Kio Street 53, Singapore
Additional Location Information slip road from Ang Mo Kio Street 53 to Ang Mo Ave 5
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMU5089Y

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Sugiharcin Widjaja Jakub
NRIC No SXXXX986B
Email Address chealse@yahoo.com
Mobile Phone No (Phone) +65-98765674
Alternative Phone No (Home) +65-98765674

VEHICLE PARTICULARS

Manufacturer Honda
Model Hr-v
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1500

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 20-MR004545-R00
Cover Note Number -

DRIVER

Name of Driver Sugiharcin Widjaja Jakub
NRIC No SXXXX986B

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes and packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

✓ Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A - Snu 5029Y

B - SL22167K